

APPENDIX E

RECLAMATION ACTIVITIES

2013 Historical Drill Site Reclamation





Hole Number (s)	Location	Year Drilled	Easting	Northing	Material removed from Site		Material Cut Off	
12GSE217	Umwelt	2012	430786	7270498	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
11GSE075	Umwelt	2011	430737	7270523	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
10GSE99	Umwelt	2010	430509	7270129	☐ Timbers Removed ☐ Water Line ☐ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
12GSE173, 173WI, 173W2	Umwelt	2012	430883	7270497	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing	☐ Anchor
12GSE236	Umwelt	2012	430941	7270495	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing	☒ Anchor
12GSE235	Umwelt	2012	430984	7270413	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing	☒ Anchor
12GSE230	Umwelt	2012	430853	7270356	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☐ Fasing	☒ Anchor
12GSE224	Umwelt	2012	430738	7270363	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☐ Fasing	☒ Anchor
12GSE207, 12GSE207W1	Umwelt	2012	430750	7270430	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing	☒ Anchor
12GSE191, 191W1, 191W2	Umwelt	2012	430946	7270384	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☒ Fasing	☒ Anchor
12GSE174, 174W1	Umwelt	2012	430999	7270424	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☐ Fasing	☐ Anchor
12GSE241	Umwelt	2012	430987	7270210	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☒ Fasing	☒ Anchor
12GSE243	Umwelt	2012	431155	7270349	☒ Timbers Removed ☐ Water Line ☒ Metal	☒ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
12GSE215, 215W1	Umwelt	2012	430955	7270323	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☒ Fasing	☒ Anchor
12GSE164	Umwelt	2012	430572	7270516	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing	☐ Anchor
12GSE154	Umwelt	2012	430579	7270522	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing	☐ Anchor
11GSE106	Umwelt	2011	430713	7270572	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
11GSE068	Umwelt	2011	430681	7270551	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☒ Fasing	☒ Anchor
11GSE121	Umwelt	2011	430655	7270521	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
11GSE042	Umwelt	2011	430626	7270505	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☐ Anchor
12GSE160	Umwelt	2012	430647	7270708	☐ Timbers Removed ☐ Water Line ☐ Metal	☐ Matting ☐ Cuttings	☐ Fasing	☐ Anchor
11GSE094	Umwelt	2011	430588	7270665	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
11GSE089	Umwelt	2011	430626	7270632	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
11GSE057	Umwelt	2011	430739	7270599	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☒ Fasing	☒ Anchor
11GSE088	Umwelt	2011	430782	7270625	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor

Hole Number (s)	Location	Year Drilled	Easting	Northing	Material removed from Site		Material Cut Off	
12GSE233, 233B, 233C	Umwelt	2012	430537	7270553	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing ☒ Anchor	
11GSE033	Umwelt	2011	430511	7270535	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☐ Anchor	
12GSE232	Umwelt	2012	430920	7270283	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing ☒ Anchor	
11GSE080	Umwelt	2011	430574	7270462	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☒ Fasing ☒ Anchor	
11GSE092	Umwelt	2011	430569	7270584	☐ Timbers Removed ☐ Water Line ☐ Metal	☐ Matting ☒ Cuttings	☒ Fasing ☒ Anchor	
12GSE240	Umwelt	2012	430429	7270595	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing ☐ Anchor	
11GSE028	Umwelt	2011	430432	7270602	☒ Timbers Removed ☐ Water Line ☐ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☐ Anchor	
11GSE116	Umwelt	2011	430467	7270611	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☒ Anchor	
11GSE105	Umwelt	2011	430509	7270672	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☒ Anchor	
12GSE234	Umwelt	2012	430500	7270652	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing ☒ Anchor	
11GSE083	Umwelt	2011	430499	7270722	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☒ Anchor	
11GSE047	Umwelt	2011	430442	7270739	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☒ Anchor	
11GSE123	Umwelt	2011	430533	7270652	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☒ Anchor	
11GSE037	Umwelt	2011	430388	7270699	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☒ Anchor	
11GSE043	Umwelt	2011	430389	7270701	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☒ Anchor	
11GSE096	Umwelt	2011	430347	7270728	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing ☒ Anchor	
11GSE125	Umwelt	2011	430315	7270702	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing ☒ Anchor	
11GSE050	Umwelt	2011	430507	7270792	☐ Timbers Removed ☐ Water Line ☐ Metal	☒ Matting ☐ Cuttings	☒ Fasing ☒ Anchor	
11GSE122	Umwelt	2011	430342	7270789	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☒ Anchor	
11GSE109	Umwelt	2011	430351	7270795	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing ☒ Anchor	
11GSE052	Umwelt	2011	430298	7270752	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☒ Anchor	
11GSE118	Umwelt	2011	430268	7270787	☒ Timbers Removed ☐ Water Line ☒ Metal	☒ Matting ☐ Cuttings	☒ Fasing ☒ Anchor	
11GSE023	Umwelt	2011	430245	7270707	☐ Timbers Removed ☐ Water Line ☐ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☐ Anchor	
11GSE026	Umwelt	2011	430331	7270651	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☐ Anchor	
11GSE031	Umwelt	2011	430233	7270761	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☐ Anchor	
11GSE128	Umwelt	2011	430198	7270765	☐ Timbers Removed ☐ Water Line ☒ Metal	☒ Matting ☐ Cuttings	☒ Fasing ☒ Anchor	
11GSE078	Umwelt	2011	430195	7270727	☐ Timbers Removed ☐ Water Line ☐ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☒ Anchor	
12GSE208	Umwelt	2012	430183	7270748	☒ Timbers Removed ☐ Water Line ☐ Metal	☐ Matting ☐ Cuttings	☐ Fasing ☒ Anchor	
10GSE126	Umwelt	2010	430147	7270820	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing ☒ Anchor	


Hole Number (s)	Location	Year Drilled	Easting	Northing	Material removed from Site		Material Cut Off	
10GSE132	Umwelt	2010	430218	7270814	☐ Timbers Removed ☐ Water Line ☐ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
10GSE137	Umwelt	2010	430145	7270753	☐ Timbers Removed ☐ Water Line ☒ Metal	☒ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
11GSE006	Umwelt	2011	430252	7270843	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☐ Anchor
11GSE001	Umwelt	2011	430200	7270864	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☐ Anchor
11GSE114	Umwelt	2011	430196	7270906	☐ Timbers Removed ☐ Water Line ☐ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
10GSE146	Umwelt	2010	430149	7270887	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
12GSE229	Umwelt	2012	430236	7270952	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing	☒ Anchor
11GSE127	Umwelt	2011	430265	7270917	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
11GSE048	Umwelt	2011	430303	7270885	☐ Timbers Removed ☐ Water Line ☐ Metal	☒ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
12GSE194, 194W1, 194W2	Umwelt	2012	430818	7270463	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☐ Fasing	☒ Anchor
11GSE055	Umwelt	2011	430539	7270691	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
11GSE074	Umwelt	2011	430438	7270670	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
11GSE040	Umwelt	2011	430316	7270831	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☒ Fasing	☒ Anchor
11GSE061	Umwelt	2011	430287	7270675	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
11GSE056	Umwelt	2011	430402	7270835	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
11GSE045	Umwelt	2011	430384	7270889	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
12GSE163	Umwelt	2012	430474	7270564	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☐ Anchor
11GSE102, 102B, 102BW	Umwelt	2011	430690	7270494	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
10GSE83, 10GSE81	Umwelt	2010	429945	7270912	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
10GSE119	Umwelt	2010	430091	7270839	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing	☒ Anchor
10GSE117	Umwelt	2010	430055	7270875	☐ Timbers Removed ☐ Water Line ☐ Metal	☐ Matting ☒ Cuttings	☐ Fasing	☐ Anchor
10GSE112	Umwelt	2010	430005	7270897	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☐ Fasing	☐ Anchor
11GSE108	Umwelt	2011	429990	7271015	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☒ Fasing	☒ Anchor
11GSE099	Umwelt	2011	430112	7270915	☒ Timbers Removed ☐ Water Line ☒ Metal	☒ Matting ☐ Cuttings	☐ Fasing	☐ Anchor
11GSE130	Umwelt	2011	430084	7270930	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing	☐ Anchor
10GSE142	Umwelt	2010	430061	7270944	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☐ Cuttings	☐ Fasing	☐ Anchor
10GSE150	Umwelt	2010	430009	7270966	☐ Timbers Removed ☐ Water Line ☐ Metal	☐ Matting ☒ Cuttings	☒ Fasing	☒ Anchor
12GSE227	Umwelt	2012	430116	7270983	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☐ Fasing	☒ Anchor
10GSE073	Umwelt	2010	429840	7270949	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☒ Fasing	☒ Anchor

Hole Number (s)	Location	Year Drilled	Easting	Northing	Material removed from Site		Material Cut Off	
10GSE136	Umwelt	2010	429888	7270926	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☐ Casing	☒ Anchor
10GSE109	Umwelt	2010	429785	7270908	☐ Timbers Removed ☐ Water Line ☐ Metal	☐ Matting ☐ Cuttings	☒ Casing	☒ Anchor
10GSE122	Umwelt	2010	429720	7270920	☐ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☐ Casing	☒ Anchor
97LA-007	Umwelt	1997	429709	7270854	☒ Timbers Removed ☐ Water Line ☒ Metal	☐ Matting ☒ Cuttings	☐ Casing	☒ Anchor



2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation





2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation





2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation





2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation





2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation





2013 Historical Drill Site Reclamation





2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation






2013 Historical Drill Site Reclamation



2013 Historical Drill Site Reclamation



2013 Historical Drill Site Reclamation



2013 Historical Drill Site Reclamation

