

NWB Annual Report

Year being reported: 2017

License No: 2BE-GRE1621 Issued Date: October 6, 2016
 Expiry Date: October 5, 2021

Project Name: Greyhound Project

Licensee: Aura Silver Resources Inc.

Mailing Address: 5560, Main St.
 P.O. Box 279
 Manotick, ON
 K4M 1A3

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Agnico Eagle Mines Ltd.

General Background Information on the Project (*optional):

Aura Silver Resources Inc. and Agnico Eagle Mines Ltd. entered into an Option Agreement on June 1st, 2014. Agnico Eagle is the operator of the project and is responsible for all permits.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Local lakes and ponds		
Water Quantity:	0	Quantity Allowable Domestic (cu.m)	
	0	Actual Quantity Used Domestic (cu.m)	
	100m ³ /day	Quantity Allowable Drilling (cu.m)	
	1634m ³ (44m ³ /day during drilling)	Total Quantity Used Drilling (cu.m)	

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☒ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

10 holes were drilled. Drill waste (cutting) was disposed of in natural depression located at a distance of at least thirty-one (31) metres from any water body and where direct flow into water body is not possible.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No spill occurred in 2017 at this project.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

The drilling casings were removed at the end of the drilling, or cut off at ground level if they could not be removed. A final inspection by a technician was made when the drilling was completed to ensure that no remaining waste or material was present.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details attached



Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details attached



Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Inspection and Compliance Report received by the Licensee (Date):



Additional Details: (Dates of Report, Follow-up by the Licensee)

No inspection and compliance report received

Any additional comments or information for the Board to consider**Date Submitted:**

March 19, 2018

Submitted/Prepared by:

David Frenette, Environmental Coordinator

Contact Information:**Tel:** 819-874-5980 ext. 3622**Fax:****email:** david.frenette@agnicoeagle.com