

NWB Annual Report

Year being reported:2021

License No:2BE-GRE2126

Issued Date:October 6, 2021

Expiry Date:October 5, 2026

Project Name:

Greyhound Exploration Project

Licensee:

Agnico Eagle Mines Ltd.

Mailing Address:

765 chemin de la mine Goldex
Val-d'Or, Qc
J9P 7G4

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Aura Silver Resources Inc. and Agnico Eagle Mines Ltd. entered into and Option Agreement on June 1st, 2014. Agnico Eagle is the operator of the project and is responsible for all permits.

Licence Requirements: the licensee must provide the following information in accordance with

Part B

▼

Item 2

▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):Local lakes and ponds

Water Quantity:

| | |
|-------------------|--------------------------------------|
| 0 | Quantity Allowable Domestic (cu.m) |
| 0 | Actual Quantity Used Domestic (cu.m) |
| 100m³/day | Quantity Allowable Drilling (cu.m) |
| 2120m3 (59m3/day) | Total Quantity Used Drilling (cu.m) |

Waste Management and/or Disposal

☐ Solid Waste Disposal

☐ Sewage

☒ Drill Waste

☐ Greywater

☐ Hazardous

☐ Other:

Additional Details:

9 holes were drilled. Drill waste (cutting) was disposed of in natural depressions located at a distance of at least 31 meters from any water body and where direct flow into water body is not possible.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:

(as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No unauthorized discharge in 2021.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

▼

Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed

▼

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

The drilling casings were removed at the end of the drilling, or cut off at ground level if they could not be removed. A final inspection was made when the drilling was completed to ensure that no remaining waste or material was present.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details attached

▼

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details attached

▼

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC

▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:
Submitted/Prepared by:
Contact Information:

| | |
|---|--|
| March 31, 2022 | |
| David Frenette, Environmental Coordinator | |
| Tel: | 819-874-5980 ext. 4103622 |
| Fax: | |
| email: | david.frenette@agnicoeagle.com |