



17 October 2014

North Arrow Minerals Inc
Suite 800 – 625 Howe Street
Vancouver, BC V6C-2T6

RE: Land Use Permit # N2011C0003 (ORO Project) Roberts Bay area Camp and 2 Drill Holes
Associated with Water Licence # 2BE-HBP1116

On August 6, 2014 I conducted a Field Inspection at the above mentioned locations.

A copy of my Environmental Inspection Report and 3 Photo Sheets are attached.

Issues identified during the Inspection:

1 Roberts Lake Camp located at N 68° 10' 21.0" & W 106° 33' 35.8"

This area has been cleaned up nicely, only Core Boxes and Core remain.

2 Drill Site #1 located at N 68° 15' 10.2" & W 106° 34' 09.8"

Drill Collar cut within 6 inches of the ground.

3 Drill Site #6 located at N 68° 15' 04.7" & W 106° 34' 21.5"

Drill Collar cut within 6 inches of the ground.

I RECOMMEND CLOSURE OF THIS LAND USE PERMIT

Please do not hesitate to contact me should you have any questions or concerns.

Koana,

Baba Pedersen
Resource Management Officer
Aboriginal Affairs and Northern Development Canada
P.O. Box 278
Kugluktuk, NU X0B – 0E0
Phone 867-982-4306
Cell 867-222-2839
Fax 867-982-4307
Email baba.pedersen@aandc.gc.ca

cc. Land Administrator, AANDC, Iqaluit, NU

ENVIRONMENTAL INSPECTION REPORT

Permittee: (complete name and address) NORTH ARROW MINERALS INC

SUITE 800-625 HOWE ST., VANCOUVER, BC V6C 2T6

		Permit Expiry Date	Last Previous Inspection
Land Use Permit No.	N2011C0003	29 MAR 2014	12 JULY 2013
Quarrying Permit No.			
Contractor:		Subcontractor:	

Location(s) Inspected: ROBERTS BAR CAMP AND 2 DRILL HOLES

① CAMP AT N 68° 10' 21.0" W 106° 33' 35.8"

Current Stage of Operation: COMPLETED, FINAL PLAN SUBMITTED

② NAM DRILL 1 AT N 68° 15' 10.2" W 106° 34' 09.8"

Program Modifications Approved:

③ NAM DRILL 6 AT N 68° 15' 04.7" W 106° 34' 21.5"

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable

Operating Condition		Aspect Inspected			
		①	②	③	
A	Location as Permitted	A	A	A	
B	Timing as Permitted	A	A	A	
	Equipment as Approved				
D	Methods & Techniques				
E	Facilities				
F	Erosion				
G	Chemicals, Waste				
H	Wildlife & Fisheries Habitat				
I	Ecological Resource				
K	Fuel Storage				
L	Brush Disposal				
M	Matters Not Inconsistent				
N	Water Engineering				
O	Water Supply				
P	Restoration	A	A	A	
Q	Quarrying Methods				
R	Sections 12 to 19 T.L.U.R.	A	A	A	
S					
T					

Surveillance Network Program

Explanatory Remarks (attach page 2, if required) THE CAMP AREA HAS BEEN CLEANED UP VERY NICELY AND BOTH DRILL COLLARS HAVE BEEN CUT WITHIN 6 INCHES OF GROUND.

I RECOMMEN CLOSURE OF LUP.

Page 2 attached ☐ Yes ☒ No

Representative's Signature

BP

RMO Initials

Inspector's Signature

District Mgr. Initials

①

N2011C0003

ROBERTS BAY AREA CAMP

6 AUG 2014



② N7011C0003

DRILL 1

6 AUG 2014



3



N 2011 C0003

DRILL 6

6 AUG 2014

