

NWB Annual Report

Year being reported: 2013

License No: 2BE-HBP1116 Issued Date: May 27, 2011
 Expiry Date: November 30, 2016

Project Name: Hope Bay Oro Project

Licensee: North Arrow Minerals Inc.

Mailing Address: Suite 960 - 789 West Pender Street
 Vancouver, BC
 Canada V6C 1H2

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

There has not been any work done on the project since 2011.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	See Coordinates	
Water Quantity:	2	Quantity Allowable Domestic (cu.m)
	1.1	Actual Quantity Used Domestic (cu.m)
	52	Quantity Allowable Drilling (cu.m)
	36.29	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

See Appended Report

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

There has not been any work done on the project since 2011, therefore the time that the spill was noted is considered to be the date which the inspector visited the site and noted leaking fuel drums. Submitted with 2012 Annual Report.

Revisions to the Spill Contingency Plan

Select 

Additional Details:

Submitted with 2012 Annual Reporting Form as a separate document.

Revisions to the Abandonment and Restoration Plan

Select 

Additional Details:

Submitted with 2012 Annual Reporting Form as a separate document.

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

None required to date, future work as per Abandonment and Restoration Plan

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A) 

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A) 

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Inspection Report received by the Licensee (Date): ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Inspection report received by the licensee Aug. 12, 2013

Any additional comments or information for the Board to consider

None

Date Submitted:

Feb. 6, 2014

Submitted/Prepared by:

Mike MacMorran

Contact Information:

Tel: 604-668-8355

Fax: 604-689-5041

email: mike.macmorran@gmail.com,
mmacmorran@northarrowminerals.com