

NWB Annual Report

Year being reported: 2011

License No: 2BE-HEE0712

Issued Date: September 27, 2005

Expiry Date: September 30, 2012

Project Name: Heequo Property

Licensee: Diamondex Resources Ltd.

Mailing Address:
P.O. Box 11584, Suite 1410
650 West Georgia Street
Vancouver, British Columbia V6B 4N8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Same as above.

General Background Information on the Project (*optional):

The Heequo camp was removed in 2008. Site was not occupied in 2011.

Licence Requirements: the licensee must provide the following information in accordance with

Part B | Item 2

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Domestic - unnamed lake adjacent to the camp	
Water Quantity:	5 cu.m/day	Quantity Allowable Domestic (cu.m)
	0 cu.m/day	Actual Quantity Used Domestic (cu.m)
	55 cu.m/day	Quantity Allowable Drilling (cu.m)
	0 to date	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
- ☐ Sewage
- ☐ Drill Waste
- ☐ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

The camp was removed in 2008 and site was not occupied in 2011.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: No spills (as reported to the Spill Hot-line)
 Date of Spill: Not applicable
 Date of Notification to an Inspector: Not applicable
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A)

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details attached

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

--

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

--

Any responses or follow-up actions on inspection/compliance reports

Inspection and Compliance Report received by the Licensee (Date):

Additional Details: (Dates of Report, Follow-up by the Licensee)

October 7, 2013.

Any additional comments or information for the Board to consider

--

Date Submitted:

December 16, 2013

Submitted/Prepared by:

Deborah Chadwick

Contact Information:

Tel:	604-687-6644
-------------	--------------

Fax:	604-687-1448
-------------	--------------

email:	dchadwick@diamondex.net
---------------	--

GPS Coordinates for water sources utilized

[illegible]

GPS Locations of areas of waste disposal

[illegible]