

## NWB Annual Report

Year being reported: 2012



License No: 2BE-HEE0712 Issued Date: September 27, 2005  
 Expiry Date: September 30, 2012

Project Name: Heequo Property

Licensee: Diamondex Resources Ltd.

Mailing Address: P.O. Box 11584, Suite 1410  
 650 West Georgia Street  
 Vancouver, British Columbia V6B 4N8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Same as above.

## General Background Information on the Project (\*optional):

The Heequo camp was removed in 2008. Site was not occupied in 2012.

Licence Requirements: the licensee must provide the following information in accordance with

Part B



Item 2



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Domestic - unnamed lake adjacent to the camp	
Water Quantity:	5 cu.m/day	Quantity Allowable Domestic (cu.m)
	0 cu.m/day	Actual Quantity Used Domestic (cu.m)
	55 cu.m/day	Quantity Allowable Drilling (cu.m)
	0 to date	Total Quantity Used Drilling (cu.m)

## Waste Management and/or Disposal

- ☐ Solid Waste Disposal  
☐ Sewage  
☐ Drill Waste  
☐ Greywater  
☐ Hazardous  
☐ Other:

Additional Details:

The camp was removed in 2008 and site was not occupied in 2012.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:  (as reported to the Spill Hot-line)  
 Date of Spill:   
 Date of Notification to an Inspector:   
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

### Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

### Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Not Applicable (N/A)



Additional Details:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Details attached



Additional Details:

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

Inspection and Compliance Report received by the Licensee (Date): ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

October 7, 2013.

**Any additional comments or information for the Board to consider**

**Date Submitted:**

December 16, 2013

**Submitted/Prepared by:**

Deborah Chadwick

**Contact Information:**

**Tel:** 604-687-6644

**Fax:** 604-687-1448

**email:** [dchadwick@diamondex.net](mailto:dchadwick@diamondex.net)