

## NWB Annual Report

Year being reported: 2006 ▼

License No: NWB2HEE0304 Issued Date: July 8, 2005  
 Expiry Date: July 31, 2007

Project Name: Heeqou Property

Licensee: Diamondex Resources Ltd.

Mailing Address: P.O. Box 11584  
 1410 - 650 West Georgia Street  
 Vancouver, BC  
 V6B 4N8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Same as above

## General Background Information on the Project (\*optional):

There was no drilling in 2006 and the camp was not used in 2006. The camp is located at 420900E / 7319300N (UTMz12, NAD83).

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.**

Water Source(s):	Domestic - unnamed lake adjacent to the camp		
Water Quantity:	5 cu.m/day	Quantity Allowable Domestic (cu.m)	
	0 cu.m/day	Actual Quantity Used Domestic (cu.m)	
	25 cu.m/day	Quantity Allowable Drilling (cu.m)	
	0 to date	Total Quantity Used Drilling (cu.m)	

## Waste Management and/or Disposal

- ☐ Solid Waste Disposal  
☐ Sewage  
☐ Drill Waste  
☐ Greywater  
☐ Hazardous  
☐ Other:

Additional Details:

**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.:  (as reported to the Spill Hot-line)  
 Date of Spill:   
 Date of Notification to an Inspector:   
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

#### Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

#### Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed

Additional Details:

#### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

#### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Additional Details:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Additional Details:

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

No inspection and/or compliance report issued by INAC

Additional Details: (Dates of Report, Follow-up by the Licensee)

**Any additional comments or information for the Board to consider**

**Date Submitted:**

March 12, 2007

**Submitted/Prepared by:**

Janet Stritychuk, Land Manager

**Contact Information:**

**Tel:** (604) 687 6644

**Fax:** (640) 687 1448

**email:** [jstrychuk@diamondex.net](mailto:jstrychuk@diamondex.net)