

Nunavut Water Board

Standard Form for Annual Reporting Requirements of NWB2 Exploration Water Licenses

Under the terms of your water licence issued by the Nunavut Water Board ("NWB") for the use of water and the disposal of waste into water associated with mineral exploration (NWB2 Licenses), Licensees are required to submit to the NWB an Annual Report no later than March 31st of the year following the calendar year being reported.

In order to aid the Licensee with the preparation of the Annual Report and facilitate its review by the NWB, Licensees are **required** to use the following form.

Recommendation and Helpful tips for use:

Metric units shall be used to report any relevant data.

How to Add additional space within Text boxes - Right click mouse on the row number (directly to the left of your screen) which falls within the text box range and click insert. **Do not drag or drop text box to modify size of the text box because formatting will not be maintained and data will be lost.** If you have large amounts of data recommend adding additional worksheets. Go to the help menu for assistance.

Electronic versions should be submitted in Adobe to ensure protection of your information. If you do not have shortcut keys to save as a PDF. Go to print menu . Choose to print "Entire Worksheet" then select printer option Adobe PDF and you will be prompted to save the document as a PDF document. Reminder ensure you have saved your document in Excel so that future changes can be made.

Modify the Header - Select "View" then "Header" from the main menu. Select "Custom Header" and change to reflect the valid Water Licence No.

Textboxes denoted with * are optional.

Annual Reports shall be submitted by either fax, mail or email in adobe acrobat or Excel format to:

Nunavut Water Board
c/o Manager of Licensing
P.O. Box 119
Gjoa Haven, NU X0B 1J0
Tel: 867-360-6338
Fax: 867-360-6369
Email: licensing@nwb.nunavut.ca

NWB Annual Report

Year being reported: 2010



License No: 2BE-HEE0712

Issued Date: September 27, 2005

Expiry Date: September 30, 2012

Project Name: Heeqou Property

Licensee: Diamondex Resources Ltd.

Mailing Address: P.O. Box 11584
1410 - 650 West Georgia Street
Vancouver, BC
V6B 4N8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Same as above

General Background Information on the Project (*optional):

The Heeqou camp was removed in 2008. Site was not occupied in 2010. The camp was located at 420900E / 7319300N (UTMz12, NAD83).

Licence Requirements: the licensee must provide the following information in accordance with

Part B



Item 2



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Domestic - unnamed lake adjacent to the camp	
Water Quantity:	5 cu.m/day	Quantity Allowable Domestic (cu.m)
	0 cu.m/day	Actual Quantity Used Domestic (cu.m)
	55 cu.m/day	Quantity Allowable Drilling (cu.m)
	0 to date	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

The camp was removed in 2008 and site was not occupied in 2010.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: No spills (as reported to the Spill Hot-line)

Date of Spill: Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

There were no spills.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

SCP was submitted and approved granting of License # 2BE-HEE0712 in 2007

Revisions to the Abandonment and Restoration Plan

Other: (see additional details)

Additional Details:

AR plan was submitted in May of 2009 but could only be approved pending a satisfactory report from NWB Inspector. Inspection was undertaken on July 29, 2010 and deficiencies were noted. A Final AR Plan was submitted in June of 2011 in partial address of deficiencies noted by NWB Inspector.

On November 12, 2010 final clearance was granted for LUP#N2005C0022 following inspection of camp site on July 29 of that year.

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Camp was removed in August of 2008. No materials were left at the site, all drums removed and sumps were refilled. No drilling was ever undertaken within bounds of

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details attached

Additional Details:

To date, Diamondex has not conducted any drilling programs on the Heeqou property. The camp was removed in 2008 but when the camp was in use, the water source for domestic purposes was pumped from the lake located directly in front of the camp site.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details attached

Additional Details:

--

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board	▼
---	---

Additional Details: (date of request, analysis of results, data attached, etc)

--

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board	▼
---	---

Additional Details: (Attached or provided below)

--

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC	▼
---	---

Additional Details: (Dates of Report, Follow-up by the Licensee)

--

Any additional comments or information for the Board to consider

--

Date Submitted:

June 29, 2011

Submitted/Prepared by:

Deborah Chadwick

Contact Information:

Tel:	(604) 687 6644
-------------	----------------

Fax:	(640) 687 1448
-------------	----------------

email:	dchadwick@canterraminerals.com
---------------	--

GPS Coordinates for water sources utilized

[illegible]

GPS Locations of areas of waste disposal

[illegible]