



WATER USE INSPECTION REPORT FORM

Nunavut Water
Board

JUN 03 2014

Public Registry

Date: July 8 th , 2013	Licensee Rep. David Dehlin, Director
Licensee: Newmont Mining Corporation	License No: 2BE-HEN0508

Comments: An inspection was conducted Henik Lake Exploration Project. Due to the lack of annual reporting the project area was inspected using a spiral transect to cover the area of N61 39' 40.0" W98 06' 00.0" to N61 29' 45.45" W97 54' 00.0 which are considered to be the project boundaries.

WATER SUPPLY

Source(s): N/A	Quantity used: N/A Allowed 60 cubic meters a day
Owner:/Operator: Newmont Mining Corporation	

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Intake Facilities: N/A	Storage Structure: N/A	Treatment Systems: N/A	Chemical Storage: N/A
Flow Meas. Device: N/A	Conveyance Lines: N/A	Pumping Stations: N/A	Screen : N/A

Comments: This licence was issued for the purpose of drilling.

WASTE DISPOSAL

Comment: No signs of waste or disturbance within claim extent.

Sewage: Sewage Treatment System: BIODISK

Natural Water Body: N/A	Continuous Discharge (land or water): N/A
Seasonal Discharge: N/A	Wetlands Treatment: N/A Trench: N/A

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Discharge Quality: N/A	Decant Structure: N/A	Erosion: N/A
Discharge Meas. Device: N/A	Dyke Inspection: N/A	Seepages: N/A
Dams, Dykes: N/A	Freeboard: N/A	Spills: N/A
Construction: N/A	O&M Plan: N/A	A&R Plan: N/A
Periods of Discharge: N/A	Effluent Discharge Rate: N/A	

Comments: Nueltin Fly-in Lodge was used as the base camp and staging area for this exploration project.

FUEL STORAGE:

Owner/Operator:

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Berms & Liners: N/A	Water within Berms: N/A	Evidence of Leaks: N/A
Drainage Pipes: N/A	Pump Station & Catchments Berm: N/A	
Pipeline Condition: N/A	Condition of Tanks: N/A	

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected	Owner /Operator: Newmont Canada
0	AANDC:
Signs Posted	SNP: Warning: None
Records & Reporting: Annual Report submitted	
Geotechnical Inspection:	

General Comments:

- Over all very little was noted during the inspection with the exception of a few pieces of wood presumable steaks used during the exploration process.

Non-Compliance of Act or Licence:

- Part B item (1): Failure to pay water use fees
- Part B item (2): Failure to submit annual reports
- Part H item (1)(i-vii): Failure to submit addendum to Spill plan
- Part I item (1) and (2): Failure to revise and submit A&R plan



Comments: The Licensee shall contact the inspector upon receipt of the report by telephone at the coordinates listed below before Aug 30th, 2013.

All issues identified during this inspection have or will be address as discussed in this report.

Failure to undertake the actions required as described in this inspection report, and to the satisfaction of the Inspector, may result in enforcement action(s) being undertaken pursuant to the *Nunavut Waters and Nunavut Surface Rights Tribunal Act*.

Christine Wilson
Inspector's Name

Original signed on file
Inspector's Signature

Representative Name, Title

Representative Signature

Cc: Erik Allain- Manager Field Operations

Cc: Phyllis Beaulieu – Manager Licensing- Nunavut Water Board

Contact Information:

Christine Wilson
Resource Management Officer
Aboriginal Affairs and Northern Development Canada
Building 918 – Box 100
Iqaluit, Nunavut XOA OHO
867-975-4296 Ph
867-979-6445 Fx
Christine.Wilson@aandc.gc.ca