



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee	Licensee Representative
Adamera Minerals Corp.	N/A
Licence No. / Expiry	Representative's Title
2BE-HEP0712	-
Land / Other Authorizations	Land / Other Authorizations
N2006C0039	
Date of Inspection	Inspector
14/07/2014	Eva Paul
Activities Inspected	
<input type="checkbox"/> Camp	<input checked="" type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Mining
	<input type="checkbox"/> Construction
	<input checked="" type="checkbox"/> Reclamation
	<input type="checkbox"/> Fuel Storage
	<input type="checkbox"/> Other:

Conditions:		A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected		
Water Use	Condition	Comment	Site Conditions	Condition	Comment	Haz/Mat Management	Condition	Comment
Intake/Screen	NA		Water Management Structures	NA		Storage	NA	
Flow Measure. Device	NA		Culverts / Bridges	NA		Spills	NA	
Source:	NA		Drainage	NA		Spill Plan	NA	
Water Use:	NA		Erosion / Sediment	NA				
Recirculation (y /n)	NA		Mitigation Measures	NA		Administrative		
			Reclamation Activities	A		Records	A	
			Materials Storage	NA		Reports	A	
Waste Disposal			Signage	NA		Plans	NI	
Waste Water	A					Notifications	NA	
Solid Waste	A		Monitoring			Other		
Hazardous Waste	A		Sample Collection / Analysis	NA				
*The number in the comments field will correspond with specific comments provided below.								
Samples taken by Inspector:			Location(s):					
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No								

SECTION 1	<input checked="" type="checkbox"/> Comments (s.1)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.__)	<input type="checkbox"/> Action Required (s.__)
This project spans the NWT-Nunavut border. To the Inspector's understanding, this part of the border has not yet been surveyed. The Licensee has a camp on the NWT side of the border, and conducted drilling in Nunavut.			
Three drill sites were inspected within the Nunavut Territory. All were found to be reclaimed pursuant to the licence conditions. Coordinates are as follows:			
1) N66°26'41.7" W115°13'20.2"			
2) N66°28'49.8" W115°15'20.1"			
3) N66°29'06.3" W115°11'20.5"			
Should the Licensee pursue cancellation of this licence, no further inspection within Nunavut is required.			
SECTION 2	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
N/A			
SECTION 3	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
N/A			

Licensee or Representative	Inspector's Name
	Eva Paul
Signature	Signature
	Sent electronically
Date	Date
	27/10/2014

APPENDICES:	<input type="checkbox"/> Inspection Photos	<input type="checkbox"/> Sample Results	<input type="checkbox"/> Other: _____
-------------	--	---	---------------------------------------

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---

CC: Phyllis Beaulieu, Manager of Licensing, NWB
Erik Allain, Manager of Field Operations, AANDC
Tracey McCaie, Manager of Lands Administration, AANDC
Baba Pedersen, Resource Management Officer, Kitikmeot Region, AANDC