NWB Annual	Report	Year being reported: 2007 ▼	
License No:	2BE-HEP0712	Issued Date: February 26, 2007	
		Expiry Date: December 31, 2012	
	,		
	Project Name:	Hepburn Project	
	Diaman	de Newth December 14d	
	Licensee: Diamon	ds North Resources Ltd.	
		[510 510 D	
	Mailing Address:	510 - 510 Burrard Street Vancouver, BC	
		V6C 3A8	
		phone: 604-689-2010	
	Name of Company	filing Annual Report (if different from Name of Licensee please clarify	
		e two entities, if applicable):	
	Diamonds North Resource	ees Ltd.	
Conoral Boo	karound Information	on the Project (tautional)	
General bac	kground information	n on the Project (*optional):	
l			
Licence Rea	uirements: the licen	see must provide the following information in accodance	
with			
	Select ▼ S	Select $lacktriangle$	
_			
_		and waste disposal activities, including, but not limited to: methods o	i
		eywater management; drill waste management; solid and hazardous	
waste manaç		Hepburn lake - used as a drinkable water source for camp	
	Water Source(s):		
	Water Quantity:	GO Quantity Allowable Domestic (cu.m) LESS THAN 30 Actual Quantity Used Domestic (cu.m)	
		n/a Quantity Allowable Drilling (cu.m)	
		compressed air Total Quantity Used Drilling (cu.m)	
		rotal additity ood Diming (daili)	
	Waste Management	and/or Disposal	
	Solid Waste Dis	posal	
	Sewage		
	Drill Waste		
	Greywater		
	Hazardous		
	Other:		
1	Additional Details:	a a latring hit legated at a distance greater than 20m away from Herriburn Lake	
		n a latrine pit located at a distance greater than 30m away from Hepuburn Lake in a pit behind kitchen tent at a distance greater than 30m from Hepburn Lake	
		compressed air was used instead of water - and drill chips were disposed of in	
	an annioriate natural deni	ression located at least a distance of 30m from the oridnary high water mark of	

A list of unauthorized discharges and a summary of follow-up actions taken.

	Spill No.: n/a (as reported to the Spill Hot-line)
	Date of Spill: n/a Date of Notification to an Inspector: n/a
	Date of Notification to an Inspector: n/a Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)
	no spills.
Revisio	ns to the Spill Contingency Plan
	SCP submitted and approved - no revision required or proposed
	Additional Detailer
	Additional Details: The Contingency plan was reviewed in 2008 and a copy is submitted with this report.
Davisia	no to the Albandan mant and Destauration Diag
Revisio	ns to the Abandonment and Restoration Plan No Abandonment and Restoration (AR) Plan submitted or approved
	No Abandoniment and Restoration (AR) Plan Submitted of approved
	Additional Details:
Progres	sive Reclamation Work Undertaken
	Additional Details (i.e., work completed and future works proposed)
	The Hepburn Property straddles both NWT and NU - with the majority of land falling in NWT. 21 shallow drill holes were completed over the Hepburn Property in 2007 - 6 holes are located in Nunavut, and the remainder (15 holes) in NWT. Clint Ambrose and Ken Dalton (land inspectors for NWT) conducted a
Results	of the Monitoring Program including:
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of
	each location where sources of water are utilized;
	Select ▼
	Additional Details:
	Hepburn Camp: 575144E 7359827N , Nad 83, zone 11.
	66.34906N 115.32122W
	66°20'56.7N 115°19'16.2W
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of
	each location where wastes associated with the licence are deposited;
	Select ▼
	Additional Details:
	shallow drill holes (compressed air drilling) - maximum depth 300 feet.
	21 drill holes: Drill hole ID, EASTING, NORTHING (NAD 83, ZONE 11)
	07HEP31-RC1 579268 7370630

Results of any additional sampling and/or analysis that was requested by an Inspector

	No additional sampling requested by an Inspector or the Board			
	Additional Details: (date of request, analysis of results, data attached, etc)			
Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.				
	No additional sampling requested by an Inspector or the Board			
	Additional Details: (Attached or provided below)			
Any respons	s or follow-up actions on inspection/compliance reports			
	No inspection and/or compliance report issued by INAC ▼			
,	Additional Details: (Dates of Report, Follow-up by the Licensee)			
Any addition	I comments or information for the Board to consider			
Date Submitt Submitted/Pi Contact Info	pared by: Shellie Jober			