

NWB Annual Report

Year being reported: 2008



License No: 2BE-HEP0712

Issued Date:

February 26, 2007

Expiry Date:

December 31, 2012

Project Name:

Hepburn Project

Licensee:

Diamonds North Resources Ltd.

Mailing Address:

510 - 510 Burrard Street
 Vancouver, BC
 V6C 3A8
 phone: 604-689-2010

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Diamonds North Resources Ltd.

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B



Item 2



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

N/A No water used within the Nunavut portion of the project area

Water Quantity:

60 total

Quantity Allowable Domestic (cu.m)

0; no drilling, no
 camp within
 Nunavut

Actual Quantity Used Domestic (cu.m)

n/a

Quantity Allowable Drilling (cu.m)

n/a

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☐ Solid Waste Disposal☐ Sewage☐ Drill Waste☐ Greywater☐ Hazardous☐ Other:

Additional Details:

n/a

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

no spills.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

n/a

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

n/a

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

The Hepburn Property straddles both NWT and NU - with the vast majority of land falling in NWT. In 2008 till sampling, prospecting and 26 ground magnetic surveys were conducted within Nunavut. As no surface disturbance is associated with this type of activity no reclamation work was required.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A) ▼

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A) ▼

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:

November 12, 2008

Submitted/Prepared by:

Shellie Jober

Contact Information:

Tel:

604 689-2010

Fax:

604 484-7143

email:

SJober@diamondsnorth.com