

NWB Annual Report

Year being reported: 2009 ▼

License No: 2BE-HEP0712

Issued Date: February 26, 2007

Expiry Date: December 31, 2012

Project Name: Hepburn Project

Licensee: Diamonds North Resources Ltd.

Mailing Address: 510 - 510 Burrard Street
Vancouver, BC
V6C 3A8
phone: 604-689-2010

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Diamonds North Resources Ltd.

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼

Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	N/A No water used within the Nunavut portion of the project area	
Water Quantity:	60 total	Quantity Allowable Domestic (cu.m)
	0; no drilling, no camp within Nunavut	Actual Quantity Used Domestic (cu.m)
	n/a	Quantity Allowable Drilling (cu.m)
	n/a	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

n/a

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

no spills.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

n/a

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

n/a

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

The Hepburn Property straddles both NWT and NU - with the vast majority of land falling in NWT. In 2009 limited prospecting was conducted within Nunavut over a 3 day period. As no surface disturbance is associated with this type of activity no reclamation work was required.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A) ▼

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A) ▼

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:

November 24, 2009

Submitted/Prepared by:

Graham Gill

Contact Information:

Tel:

604 689-2010

Fax:

604 484-7143

email:

ggill@diamondsnorthresources.com