



☒ Original
☐ Follow-Up Report

Licensee	Licensee Representative
MMG	Peter Cullinane
Licence No. / Expiry	Representative's Title
2BE-IZO1217	Field Program Manager
Licence No. / Expiry	Land / Other Authorizations
2BE-HIG1217	
Date of Inspection	Inspector
July 14 and 15, 2015	Eva Paul
Activities Inspected	
☒ Camp	☐ Drilling
☐ Roads/Hauling	☐ Mining
☐ Other:	☐ Construction
	☒ Reclamation
	☒ Fuel Storage
	☐ Other:

Conditions:	A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected
Water Use					

[illegible]

*The number in the comments field will correspond with specific comments provided below.

Samples taken by Inspector:	Location(s):
☐ Yes ☒ No	

☒ **Comments (s.1 and 2)** ☐ **Non-Compliance with Act or Licence (N/A)** ☐ **Action Required (N/A)**

MMG is preparing its two Nunavut projects for longer-term closure. An inspection was conducted on July 14 and 15 of camps and reclamation activities pertaining to MMG's 2BE-IZO1217 and 2BE-HIG1217 licences.

Izok Lake Project: Ham Lake Camp (N65°41'08, W112°52'49) and Hood Core Facility (N66°05'04", W112°43'06")

High Lake Project: High Lake Camp (N67°22'44", W110°50'40") and High Lake East/Moly Mag Camp (N67°08'36", W109°52'03")

I was accompanied by Peter Cullinane, Field Program Manager for the projects. MMG graciously hosted me for several days at Izok to conduct work in the area, allowing for a fulsome understanding of the work that has been undertaken at these sites. It is clear from the state of the camps that MMG's focus this season has been to eliminate any environmental liability from the closure of the projects. Work was completed at High Lake in the spring, and three people were on-site at Izok to carry out the camp closure.

1. An impressive amount of waste has been backhauled. Nothing but neatly stacked drill rod was in evidence at High Lake. Several more loads were anticipated from Izok following my inspection. Backhaul records were available for inspection.
2. Peter indicated that hazardous waste is all anticipated to be removed from site at Izok, and has been removed from High Lake. The few waste barrels that remain at Izok are currently in use, labelled, and contained within a berm.



SECTION 2

☒ Comments

☐ Non-Compliance with Act or Licence

☐ Action Required

3. The footprint of the facilities has been greatly reduced, and areas no longer in use have been contoured and are restricted from access to promote re-vegetation. Several tents were removed from High Lake, as well as the core/cutting shacks. High Lake East (Moly Mag) has been completely removed with only core racks remaining. Drilling equipment that remains at Izok is ready for backhaul
4. MMG is working with a nearby project to re-distribute consumables such as fuel, drill lubricants, and drill salt. All fuel and drill supplies were removed from High Lake. Peter indicated that all the remaining fuel at Izok would be consumed or removed from site prior to closure. Bulk fuel tanks have been emptied and swabbed out to prevent any potential for leakage. Vents and hoses are sealed. Only minimal hazardous materials will remain on-site, and those are in containment and within structures. The majority of the vehicles and equipment have been drained of fluids to eliminate leaks.
5. I am impressed with the measures that have been taken to all-but-eliminate potential future environmental liability from this site. Occasional monitoring of the remaining facilities will be required, and if permanent closure of the sites are sought, or cancellation of the water licences, then all of the requirements of the Abandonment and Restoration Plan, as well as of the Licence (Part I) must be met.

It has been a pleasure to inspect and work out of MMG's sites since I came to AANDC. MMG's excellent standing in compliance and environmental stewardship has made a mark in the region (as well as removing many) under Peter's leadership.

SECTION 3

☐ Comments

☐ Non-Compliance with Act or Licence

☐ Action Required

N/A

Licensee or Representative

Inspector's Name

PETER CULLINANE

Eva Paul

Signature

Signature

Date

Date

JULY 16 2015

16-7-15

Office Use Only: Follow-up report to be issued by Inspector

☐ Yes ☒ No