NWB Annual Report	Year being reported: Select ▼ 2019				
License No: 2BE-HIG1722	Issued Date: AUGUST 4, 2017 Expiry Date: AUGUST 3, 2022				
Project Name:	HIGH LAKE				
Licensee: MMG RESOURCES INC.					
Mailing Address:	MMG Resources Inc. PO BOX 91460 West Vancouver, BC,				
Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable): N/A					

General Background Information on the Project (*optional):

The site dates to the 1950s when the High Lake gossan was first identified by then Texas Gulf. It has since been explored by several groups. MMG acquired the project through a series of transactions starting with the purchase of Wolfden Resources by Zinifex in 2007. Zinifex later became Oz Minerals and subsequently was bought by MMG in 2009. The last exploration activity conducted from the site was carried out in 2013. The site saw limited occupation over the next two years while reclamation work was carried out. The last occupancy was August 2015, and as of this time the footprint was effectively reduced to the surface lease. Closure of land use permits with both KIA and AANDC was applied for at this time. MMG received approval for closure of KIA permit KTL308C008. AANDC approval for closure was originally expressed informally but later questioned and subsequently observed. The LUP N2011C0033 is still awaiting closure sign off.

The water license was renewed in 2017, as the site is considered a strategic location from which to base engineering and environmental work related to the Greys Bay road proposal. The most recent site visit was made in August 2019.

Licence Requirements: the licensee must provide the following information in accordance with

Part A ▼ Item 1 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management. <u>See additional tab "Additional Information".</u>

Water Source(s): High Lake (domestic) Surrounding (drilling)

	Water Quantity:	5	Quantity Allowable Domestic (cu.m)	
		0	Actual Quantity Used Domestic (cu.m)	
		95	Quantity Allowable Drilling (cu.m)	
		0	Total Quantity Used Drilling (cu.m)	
	generated. A one da	ccupied during the site visit was consistent of the site visit was	e 2019 season and therefor no waste was onducted 15 August 2019 by Discovery it from MMG Resources. See appended rmation" tab.	
A list of una			of follow-up actions taken.	
	Spill No.: Date of Spill:	(as	reported to the Spill Hot-line)	
	Date of Notification to	an Inspector		
		•	tion measures, short/long term monitoring, etc)	
		<u> </u>		
	N/A			
				_
Revisions to	the Spill Contingend	cy Plan		
	SCP submitted and appro	ved - no revision requ	uired or proposed	
	Additional Details:			
			CI	7
	A 2013 version of th	nis document is o	n file with NWB.	
				_
Revisions to	the Abandonment a			
	AR plan submitted and ap	proved - no revision	required or proposed	
	Additional Details:			
	A 2013 version of th	nic document is o	o filo with NIMP]
	A 2013 VEISION OF U	iis document is of	ifflie with NWB.	
Progressive	Reclamation Work U	Indertaken		
Flogressive			I and future works proposed)	
		· · · · · · · · · · · · · · · · · · ·		7
	1		5 August 2019. There was evidence wildlife	
		tures at the site a	nd a clean up was conducted. See attached	
	photo document.			

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and lor each location where sources of water are utilized; Not Applicable (N/A) Additional Details: Site was un-occupied in 2019 as it is on long term care and maintenance. No water usage occurred. The GPS Co-ordinates (in degrees, minutes and seconds of latitude and lor each location where wastes associated with the licence are deposited; Not Applicable (N/A) Additional Details: Site was un-occupied in 2019 as it is on long term care and maintenance. No waste generation occurred. Results of any additional sampling and/or analysis that was requested by a No additional Details: (date of request, analysis of results, data attached, etc) where details on water use or waste disposal requested by the Board by November 1 reported. No additional Details: (Attached or provided below) esponses or follow-up actions on inspection/compliance reports Inspection and Compliance Report received by the Licensee (Date):	
each location where sources of water are utilized; Not Applicable (N/A) Additional Details: Site was un-occupied in 2019 as it is on long term care and maintenance. No water usage occurred. The GPS Co-ordinates (in degrees, minutes and seconds of latitude and lor each location where wastes associated with the licence are deposited; Not Applicable (N/A) Additional Details: Site was un-occupied in 2019 as it is on long term care and maintenance. No waste generation occurred. Results of any additional sampling and/or analysis that was requested by a No additional sampling requested by an Inspector or the Board Additional Details: (date of request, analysis of results, data attached, etc) ther details on water use or waste disposal requested by the Board by November 1 reported. No additional sampling requested by an Inspector or the Board Additional Details: (Attached or provided below)	ng Program including:
Additional Details: Site was un-occupied in 2019 as it is on long term care and maintenance. No water usage occurred. The GPS Co-ordinates (in degrees, minutes and seconds of latitude and lor each location where wastes associated with the licence are deposited; Not Applicable (N/A) Additional Details: Site was un-occupied in 2019 as it is on long term care and maintenance. No waste generation occurred. Results of any additional sampling and/or analysis that was requested by a No additional sampling requested by an Inspector or the Board Additional Details: (date of request, analysis of results, data attached, etc) Additional Details: (Attached or provided below) esponses or follow-up actions on inspection/compliance reports Inspection and Compliance Report received by the Licensee (Date):	
Site was un-occupied in 2019 as it is on long term care and maintenance. No water usage occurred. The GPS Co-ordinates (in degrees, minutes and seconds of latitude and lor each location where wastes associated with the licence are deposited; Not Applicable (N/A) Additional Details: Site was un-occupied in 2019 as it is on long term care and maintenance. No waste generation occurred. Results of any additional sampling and/or analysis that was requested by a No additional sampling requested by an Inspector or the Board Additional Details: (date of request, analysis of results, data attached, etc) wither details on water use or waste disposal requested by the Board by November 1 reported. No additional sampling requested by an Inspector or the Board Additional Details: (Attached or provided below)	ole (N/A)
The GPS Co-ordinates (in degrees, minutes and seconds of latitude and lor each location where wastes associated with the licence are deposited; Not Applicable (N/A) Additional Details: Site was un-occupied in 2019 as it is on long term care and maintenance. No waste generation occurred. Results of any additional sampling and/or analysis that was requested by a No additional sampling requested by an Inspector or the Board Additional Details: (date of request, analysis of results, data attached, etc) other details on water use or waste disposal requested by the Board by November 1 reported. No additional sampling requested by an Inspector or the Board Additional Details: (Attached or provided below)	Details:
each location where wastes associated with the licence are deposited; Not Applicable (N/A) Additional Details: Site was un-occupied in 2019 as it is on long term care and maintenance. No waste generation occurred. Results of any additional sampling and/or analysis that was requested by a No additional sampling requested by an Inspector or the Board Additional Details: (date of request, analysis of results, data attached, etc) Additional sampling requested by an Inspector or the Board by November 1 reported. No additional sampling requested by an Inspector or the Board Additional Details: (Attached or provided below)	
Site was un-occupied in 2019 as it is on long term care and maintenance. No waste generation occurred. Results of any additional sampling and/or analysis that was requested by a No additional sampling requested by an Inspector or the Board Additional Details: (date of request, analysis of results, data attached, etc) Other details on water use or waste disposal requested by the Board by November 1 reported. No additional sampling requested by an Inspector or the Board Additional Details: (Attached or provided below) esponses or follow-up actions on inspection/compliance reports Inspection and Compliance Report received by the Licensee (Date):	tion where wastes associated with the licence are deposited;
Results of any additional sampling and/or analysis that was requested by a No additional sampling requested by an Inspector or the Board Additional Details: (date of request, analysis of results, data attached, etc) Where details on water use or waste disposal requested by the Board by November 1 reported. No additional sampling requested by an Inspector or the Board Additional Details: (Attached or provided below) esponses or follow-up actions on inspection/compliance reports Inspection and Compliance Report received by the Licensee (Date):	Details:
Additional Details: (date of request, analysis of results, data attached, etc) where details on water use or waste disposal requested by the Board by November 1 reported. No additional sampling requested by an Inspector or the Board Additional Details: (Attached or provided below) esponses or follow-up actions on inspection/compliance reports Inspection and Compliance Report received by the Licensee (Date):	
Additional Details: (date of request, analysis of results, data attached, etc) ther details on water use or waste disposal requested by the Board by November 1 reported. No additional sampling requested by an Inspector or the Board Additional Details: (Attached or provided below) sponses or follow-up actions on inspection/compliance reports Inspection and Compliance Report received by the Licensee (Date):	any additional sampling and/or analysis that was requested by an
ther details on water use or waste disposal requested by the Board by November 1 reported. No additional sampling requested by an Inspector or the Board Additional Details: (Attached or provided below) esponses or follow-up actions on inspection/compliance reports Inspection and Compliance Report received by the Licensee (Date):	I sampling requested by an Inspector or the Board
Responses or follow-up actions on inspection/compliance reports Inspection and Compliance Report received by the Licensee (Date):	Details: (date of request, analysis of results, data attached, etc)
Additional Details: (Attached or provided below) esponses or follow-up actions on inspection/compliance reports Inspection and Compliance Report received by the Licensee (Date):	iter use or waste disposal requested by the Board by November 1 o
esponses or follow-up actions on inspection/compliance reports Inspection and Compliance Report received by the Licensee (Date):	l sampling requested by an Inspector or the Board
Inspection and Compliance Report received by the Licensee (Date):	Details: (Attached or provided below)
Inspection and Compliance Report received by the Licensee (Date):	
Additional Datailes (Dates of Depart, Follow up by the Licenses)	ad Compliance Penert received by the Licenses (Date):
Additional Details: (Dates of Report, Follow-up by the Licensee)	ia Compilance Report received by the Licensee (Date).

NWB2(insert)

Any additional comments or information for the Board to consider								
Date Submitted: Submitted/Prepared by: Contact Information:	Fax:	?						