

NWB Annual Report

Year being reported:

Select



2020

License No: 2BE-HIG1722

Issued Date: AUGUST 4, 2017

Expiry Date: AUGUST 3, 2022

Project Name: HIGH LAKE

Licensee: MMG RESOURCES INC.

Mailing Address:

MMG Resources Inc.  
PO BOX 91460  
West Vancouver, BC,  
V7V 3P1

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

N/A

## General Background Information on the Project (\*optional):

The site dates to the 1950s when the High Lake gossan was first identified by then Texas Gulf. It has since been explored by several groups. MMG acquired the project through a series of transactions starting with the purchase of Wolfden Resources by Zinifex in 2007. Zinifex later became Oz Minerals and subsequently was bought by MMG in 2009. The last exploration activity conducted from the site was carried out in 2013. The site saw limited occupation over the next two years while reclamation work was carried out. The last occupancy was August 2015, and as of this time the footprint was effectively reduced to the surface lease. Closure of land use permits with both KIA and AANDC was applied for at this time. MMG received approval for closure of KIA permit KTL308C008. AANDC approval for closure was originally expressed informally but later questioned and subsequently observed. The LUP N2011C0033 is still awaiting closure sign off. The water license was renewed in 2017, as the site is considered a strategic location from which to base engineering and environmental work related to the Greys Bay road proposal. The most recent site visit was made in August 2019.

Licence Requirements: the licensee must provide the following information in accordance with

Part A



Item 1



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management. See additional tab "Additional Information".

Water Source(s): High Lake (domestic) Surrounding (drilling)

Water Quantity:	<input type="text" value="5"/>	Quantity Allowable Domestic (cu.m)
	<input type="text" value="0"/>	Actual Quantity Used Domestic (cu.m)
	<input type="text" value="95"/>	Quantity Allowable Drilling (cu.m)
	<input type="text" value="0"/>	Total Quantity Used Drilling (cu.m)

**Waste Management and/or Disposal**

- ☐ Solid Waste Disposal  
☐ Sewage  
☐ Drill Waste  
☐ Greywater  
☐ Hazardous  
☐ Other:

**Additional Details:**

The camp was un-occupied during the 2019 season and therefor no waste was generated. No site visit was conducted due to COVID-19 pandemic.

**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

N/A

**Revisions to the Spill Contingency Plan**

SCP submitted and approved - no revision required or proposed ▼

**Additional Details:**

A 2013 version of this document is on file with NWB. The Spill Contingency Plan is scheduled to be updated in 2021.

**Revisions to the Abandonment and Restoration Plan**

AR plan submitted and approved - no revision required or proposed ▼

**Additional Details:**

A 2013 version of this document is on file with NWB. The Abandonment and Restoration Plan is scheduled to be updated in 2021.

**Progressive Reclamation Work Undertaken**

Additional Details (i.e., work completed and future works proposed)

No site visit was conducted due to COVID-19 pandemic.

**Results of the Monitoring Program including:**

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Not Applicable (N/A)



Additional Details:

Site was un-occupied in 2019 as it is on long term care and maintenance. No water usage occurred. No site visit was conducted due to COVID-19 pandemic.

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Not Applicable (N/A)



Additional Details:

Site was un-occupied in 2019 as it is on long term care and maintenance. No waste generation occurred. No site visit was conducted due to COVID-19 pandemic.

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

Inspection and Compliance Report received by the Licensee (Date):



Additional Details: (Dates of Report, Follow-up by the Licensee)

--

**Any additional comments or information for the Board to consider**

A site visit is planned for Summer 2021. NWB will be notified of exact date once it has been scheduled by Discovery Mining Services.

**Date Submitted:**

April 29, 2021

**Submitted/Prepared by:**

Sarah Hasek

**Contact Information:****Tel:** 778 358 8155**Fax:****email:** [sarah.hasek@mmg.com](mailto:sarah.hasek@mmg.com)