



Photo #1: Generator tank and spill ponded behind natural berm.



Photo #2: Standing fuel being pumped into 45 gallon drums.





Photo #3: Kabota excavating contaminated soil.



Photo #4: Transferring contaminated soil into 45 gallon drums.