Year being reported: 2016 **NWB Annual Report**

License No: 2BE-HRP1419 Issued Date: November 4, 2014

Expiry Date: November 3, 2019

Project Name: HOOD RIVER

Licensee: WPC RESOURCES INCORPORATED / INUKSHUK EXPLORATION INC.

Mailing Address: Suite 1125,

595 Howe Street,

Vancouver, British Columbia.

CANADA V6C 2T5

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Inukshuk Exploration Incorporated is 100% owned by WPC Resources Incorporated.

General Background Information on the Project (*optional):

PROJECT WILL BE INITIATED DURING 2017. No work was undertaken on the Hood River Project during 2016.

Licence Requirements: the licensee must provide the following information in accodance with

> Part B Item 2

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

> Water Source(s): NO WATER WAS USED DURING 2016: Permit allows for a

> > total of 100 m³ per year to be consumed: none is permitted for

domestic use.

Water Quantity: <u>0 m³</u> Quantity Allowable Domestic (cu.m)

Actual Quantity Used Domestic (cu.m) 0 m³ Quantity Allowable Drilling (cu.m) 100 m³ (Total) Total Quantity Used Drilling (cu.m) 0 m^3

	Waste Management and/or Disposal
	☑ Solid Waste Disposal
	☑ Sewage
	☑ Drill Waste
	☑ Greywater
	☑ Hazardous
	☐ Other:
r	Additional Details:
	NO WASTE MATERIAL WAS GENERATED ON THIS PERMIT DURING 2016.
A list of unau	uthorized disc <u>harges and a summ</u> ary of follow-up actions taken.
	Spill No.: N/A (as reported to the Spill Hot-line)
	Date of Spill: N/A
	Date of Notification to an Inspector: N/A
	Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)
	NO UNAUTHORIZED DISCHARGES OCCURRED DURING 2016 ON THIS PERMIT.
Revisions to	the Spill Contingency Plan
	SCP submitted and approved - no revision required or proposed
	Solution and approved in contract of property
	Additional Details:
	There were no revisions required to the Spill Plan.
	There were no revisions required to the Spin Flan.
Revisions to	the Abandonment and Restoration Plan
	AR plan submitted and approved - no revision required or proposed
	And plant submitted and approved a no revision required or proposed
	Additional Details:
	There were no revisions required to the Abandonment and Restoration Plan
Progressive	Reclamation Work Undertaken
	Additional Details (i.e., work completed and future works proposed)
	NO RECLAMATION UNDERTAKEN OR REQUIRED DURING 2016.

Results of the Monitoring Program including:

	Not Applicable (N/A) ▼
	Additional Details:
	NO WATER SOURCES WERE UTILIZED ON THIS PERMIT DURING 2016.
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude each location where wastes associated with the licence are deposited;
	Not Applicable (N/A) ▼
	Additional Details:
	NO WASTES ASSOCIATED WITH THIS PERMIT WERE ACCRUED DURING 2016.
	Results of any additional sampling and/or analysis that was requested by an Inspector or the Board To additional sampling requested by an Inspector or the Board
	The additional sampling requested by an inspector of the board
	Additional Details: (date of request, analysis of results, data attached, etc)
	Additional Details: (date of request, analysis of results, data attached, etc) N/A details on water use or waste disposal requested by the Board by November 1 of th
ther o	Additional Details: (date of request, analysis of results, data attached, etc) N/A details on water use or waste disposal requested by the Board by November 1 of th
	Additional Details: (date of request, analysis of results, data attached, etc) N/A details on water use or waste disposal requested by the Board by November 1 of the rted.
	Additional Details: (date of request, analysis of results, data attached, etc) N/A details on water use or waste disposal requested by the Board by November 1 of the rted. No additional sampling requested by an Inspector or the Board
repo	Additional Details: (date of request, analysis of results, data attached, etc) N/A details on water use or waste disposal requested by the Board by November 1 of the rted. No additional sampling requested by an Inspector or the Board Additional Details: (Attached or provided below) N/A
repo	Additional Details: (date of request, analysis of results, data attached, etc) N/A details on water use or waste disposal requested by the Board by November 1 of the rted. No additional sampling requested by an Inspector or the Board Additional Details: (Attached or provided below)
repo	Additional Details: (date of request, analysis of results, data attached, etc) N/A details on water use or waste disposal requested by the Board by November 1 of the rted. No additional sampling requested by an Inspector or the Board Additional Details: (Attached or provided below) N/A nses or follow-up actions on inspection/compliance reports

Any addition	al comments or information for the Board to consider	

Date Submitted:
Submitted/Prepared by:
Contact Information:

November 7, 2016

Bruce E. Goad, P. Geo. **Tel:** 604-533-2255

Fax: 604-533-2255 (once notified)

email: InukshukGeological@Shaw.ca

GPS Coordinates for water sources utilized

	Latitude			Longitude			
Source Description	o Deg	, Rii	, Sec	o Deg	, Min	, Sec	
N/A							

GPS Locations of areas of waste disposal

Location Description (type)	Latitude			Longitude			
	o Deg	, Min	, Sec	o Deg	, Min	, Sec	
N/A							
_							