| NWB Annual | Report | | | Year being repo | orted: | 2019 | |
|---|---|---|---|--|--|-------------------|-----|
| License No: | 2BE-HUC1823 | | | Issued Date: Expiry Date: | July 18, 20 October 31 | | |
| | Project Name: | F | Huckleberry | Exploration Project | t | | |
| | Licensee: | Agnico | Eagle Mine | es Ltd. | | | |
| Mailing Address: | | 765 chemin de la mine Goldex Val-d'Or, Qc J9P 7G4 | | | | | |
| | Name of Comp | - | _ | Il Report (if different if applicable): | from Name of Lice | nsee please clari | ify |
| General Bac | kground Inform | ation | on the Proj | ject (*optional): | | | |
| | | | | | | | |
| Licence Requirements: the licensee must provide the following information in accodance with | | | | | | | |
| | Part B | | m 2 | | | | |
| | iter; sewage an | | | sposal activities, i agement; drill was | | | |
| | Water Source(s): Water Quantity: | | Local lakes and ponds 5m³/day 0m³/day 294m³/day 0m³/day | | Quantity Allowable Domestic Actual Quantity Used Domestic (cu.m) Quantity Allowable Drilling Total Quantity Used Drilling | | |
| | Waste Manage Solid Was Sewage Drill Wast Greywate Hazardou Other: Additional Deta | ste Dispo te er is | | osal | | | |
| | | | ctivities cor | nducted in 2019. | | | |
| A list of unau | | arges | and a sum | mary of follow-up | | | |
| | Spill No.: Date of Spill: Date of Notifica Additional Deta | ils: (imp | acts to water, | mitigation measures, sh | | | |
| Revisions to the Spill Contingency Plan | | | | | | | |
| | SCP submitted and approved - no revision required or proposed | | | | | | |
| | Additional Deta | ils: | | | | | |
| Revisions to | the Abandonm | ent an | d Restorat | tion Plan | | | |
| | | | | vision required or propos | sed | | ▼ |

| | Additional Details: |
|--------------|--|
| | |
| | |
| Progressive | Reclamation Work Undertaken |
| J | Additional Details (i.e., work completed and future works proposed) |
| | N/A |
| | |
| | |
| Results of t | he Monitoring Program including: |
| | The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each |
| | location where sources of water are utilized; |
| | Not Applicable (N/A) |
| | Additional Details: |
| | |
| | |
| | |
| | The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each |
| | location where wastes associated with the licence are deposited; Not Applicable (N/A) ▼ |
| | |
| | Additional Details: |
| | |
| | |
| | |
| | Results of any additional sampling and/or analysis that was requested by an Inspector |
| | No additional sampling requested by an Inspector or the Board |
| | Additional Details: (date of request, analysis of results, data attached, etc) |
| | The state of the s |
| | |
| | |
| Any other d | etails on water use or waste disposal requested by the Board by November 1 of the year ted. |
| J 1 | No additional sampling requested by an Inspector or the Board |
| | Additional Details: (Attached or provided below) |
| | |
| | |
| _ | |
| Any respon | ses or follow-up actions on inspection/compliance reports No inspection and/or compliance report issued by INAC |
| | |
| | Additional Details: (Dates of Report, Follow-up by the Licensee) |
| | |
| | |
| Any additio | nal comments or information for the Board to consider |
| | |
| | |
| | |
| | |

Date Submitted:
Submitted/Prepared by:
Contact Information:

Tel:
819.874.5980 ext. 4103622

Fax:
email:
david.frenette@agnicoeagle.com