

## NWB Annual Report

Year being reported: **2018**

License No: **2BE-ILP1419** Issued Date: **February 23, 2014**  
 Expiry Date: **February 22, 2019**

Project Name: **Itchen Lake**

Licensee: **HTX MInerals Corp.**

Mailing Address: **410 FALCONBRIDGE ROAD, UNIT 5, SUDBURY, ONTARIO,  
P3A 4S4**

**Name of Company filing Annual Report** (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

**APEX Geoscience Ltd. on behalf of Transition Metals Corp. On August 14, 2013, Transition acquired all of the outstanding common shares of HTX and therefore HTX is now a private wholly owned subsidiary of Transition.**

**General Background Information on the Project** (\*optional):

**No work was completed on the Property in 2018**

**Licence Requirements: the licensee must provide the following information in accordance with**

Part B ▼ Item 2 ▼

**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.**

Water Source(s):	<b>N/A</b>	
Water Quantity:	<b>25</b>	Quantity Allowable Domestic (cu.m)
	<b>0</b>	Actual Quantity Used Domestic (cu.m)
	<b>35</b>	Quantity Allowable Drilling (cu.m)
	<b>0</b>	Total Quantity Used Drilling (cu.m)

**Waste Management and/or Disposal**

- ☐ Solid Waste Disposal  
☐ Sewage  
☐ Drill Waste  
☐ Greywater  
☐ Hazardous  
☐ Other:

**Additional Details:**

**No waste was produced in 2018**

**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

N/A

**Revisions to the Spill Contingency Plan**

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

**Revisions to the Abandonment and Restoration Plan**

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

**Progressive Reclamation Work Undertaken**

Additional Details (i.e., work completed and future works proposed)

N/A

**Results of the Monitoring Program including:**

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Not Applicable (N/A) ▼

Additional Details:

No water was used in 2018

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Not Applicable (N/A) ▼

Additional Details:

No waste was produced in 2018

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

**Any additional comments or information for the Board to consider**

**Date Submitted:**

March 29, 2019

**Submitted/Prepared by:**

Tara Gunson APEX Geoscience Ltd.

**Contact Information:**

Tel: (780) 467-3532

Fax: (780) 467-4025

email: [tgunson@apexgeoscience.com](mailto:tgunson@apexgeoscience.com)