



Photos of July 12, 2017 Inspection of MMG’s Izok/Hood Project

Date	Camera	Inspector	Authorization
12 07 2017	SONY DSC-HX50V	Eva Paul	86I/2-1-10
Photo Log # 1		Location (NAD 83 DD MM SS.SS)	
Photo DSC07561		N	W



**Description:** Small creek south of old cabins at Hood/Amooga Booga. Debris noted below date stamp in photograph.

Photo Log # 2	Location (NAD 83 DD MM SS.SS)	
Photo DSC07562	N	W



**Description:** Possible garbage on creek banks.





Photo Log # 3

Photo DSC07563

Location (NAD 83 DD MM SS.SS)

NW



Description: Old cabins and half-buried waste barrels, left too close to the OHWM.

Photo Log # 4

Photo DSC07564

Location (NAD 83 DD MM SS.SS)

NW



Description: Old cabins and debris.





Photo Log # 5

Photo DSC07566

Location (NAD 83 DD MM SS.SS)

NW



Description:

Site from the north – debris blown around.

Photo Log # 6

Photo DSC07574

Location (NAD 83 DD MM SS.SS)

N65 41 07.3W112 53 02.9



Description:

Ham Lake camp from northwest. Decommissioned fuel tanks should be removed at earliest opportunity.





Photo Log # 7

Photo DSC07583

Location (NAD 83 DD MM SS.SS)

N65 41 16.2      W112 52 46.6



Description: Ham Lake camp from the north. Debris blown onto tundra around the sauna.

Photo Log # 8

Photo DSC07599

Location (NAD 83 DD MM SS.SS)

N65 38 05.9      W112 47 02.6



Description: Drill stems left in Izok Lake.





Photo Log # 9

Location (NAD 83 DD MM SS.SS)

Photo DSC07600

N65 37 58.2

W112 47 36.8



Description: Drill stems left in Izok Lake.

Photo Log # 10

Location (NAD 83 DD MM SS.SS)

Photo DSC07601

N65 37 56.2

W112 47 45.9



Description: Drill stems left in Izok Lake.





Photo Log # 11	Location (NAD 83 DD MM SS.SS)	
Photo DSC07595	N65 38 11.1	W112 52 31.4



Description: Debris noted on Iznogoudh.

Photo Log # 12	Location (NAD 83 DD MM SS.SS)	
Photo DSC07590	N65 38 20.9	W112 52 02.2



Description: Debris noted on Iznogoudh.