



INAC Nunavut Regional Office  
Field Operations  
P.O. Box 100, Iqaluit, Nunavut, X0A 0H0

Sent via E-mail  
**CIDM #544968**

Friday, July 20, 2012

Phyllis Beaulieu  
Manager of Licensing  
Nunavut Water Board  
P.O. Box 119  
Gjoa Haven, NU X0B 1J0  
Email: [licensing@nunavutwaterboard.org](mailto:licensing@nunavutwaterboard.org)

**Re: 2012 Inspection Report of 2BE-KAZ1011 for Closure**

Ms. Beaulieu,

Further to the request by Newmount Mining Corporation for closure of the “Baker Lake Basin Project” water license 2BE-KAZ1011, located in the Kivalliq Region.

On July 11<sup>th</sup>, 2012, a compliance inspection was completed by AANDC’s, Resource Management Officer. During that inspection no compliance issues associated with the site were noted.

A copy of this Inspection Report and associated photos has been attached to this letter for your review.

After a review of this report and by copy of this letter it is the recommendation of the Field Operations Section-AANDC, that this file may be approved for closure.

Should you have any concerns with respect to this information please feel free to contact this office with any questions you may have.

Thank you,

*Original Signed this date*

---

Andrew Keim  
A/Manager - Field Operations  
Nunavut Region, Iqaluit  
[Andrew.keim@aandc.gc.ca](mailto:Andrew.keim@aandc.gc.ca)

Attached; RMO Inspection report, field form and photos



Field Inspection Photos taken July 11th, 2012



Aerial over view of camp, Ground disturbances and burn area evident



Some ground disturbances from camp structures



Ash and wood debris has been removed from burn area