NUNAVUT SPILL REPORT (Oil, Gas, Hazardous Chemicals or other Materials)

ᓄᓇᕗᑦᑕ ᑯᐱᔪᓄᑦ ᐅᓂᒃᑳᖅ (ᐅᓐᓱᐊᓗᐃᑦ, ᒐᓱᑦ, ᐋᑦᑕᓐᓂᑦ, ᐃᓚᒡᒐᐃᑦ ᐅᑦᑕᓗ ᐊᓯᔾᔨᑦ)

24-Hour Report Line 24-ᓄᑦ ᐃᑲᕐᓗᓄᑦ ᐅᓂᒃᑳᐃᐅ ᐊᓐᓇᕐᓂᕐ ᐅᖃᓚᐅᑦ
Phone/ᐅᖃᓚᐅᑦ (867) 920-8130
Fax/ᓱᑲᑦᑐᑯᑦ (867) 873-6924

A Report Date and Time ᐅᑦᓗᕐ ᓱᕋᒃᑯᓗᒃ ᑲᔪᓯᐊᕐᑎᑦᓗᒍ ᐅᓂᒃᑲᑎᑦᑎᔭᐃᑦ	B Date and Time of Spill (if known) ᐅᑦᓗᖕᒐ ᑯᐱᑎᑦᓗᒍ ᑲᔪᓯᐊᕐᑎᑦᓗᒍᓗ (ᑮᐅᔾᒪᔭᐅᑦᑕᑦ)	C ☐ Original Report ᓱᕈᓐᓂᑦᑕᑦ ᐅᓂᒃᑳᔭᐅᔪᕐ ☐ Update No. _____ ᓂᒃᑳᔭᐅᒃᑲᓂᕐᑦ ᓇᓴᐅᑦ	Spill Number ᓴᐱᔪᑦ ᓇᓴᐅᑦ
July 15/08 23:00	July 13/08		

D Location and Map Coordinates (if known) and Direction (if moving) ᓇᓂ ᑯᐱᑦ ᐊᒻᒪᓗ ᓄᓇᕐᒐᐊᑦ ᓇᓴᐅᑎᔪᑦ (ᑮᐅᔾᒪᔭᐅᑦᑕᑦ) ᐊᒻᒪᓗ ᓇᓗᕐᒐᐅᑦᓕᐊᕐᒪᕐᒪᑦ (ᐃᔪᕐᔪᑦ)

Areva Kiggavik Site - Bong Lease 562323 7144084

E Party Responsible for Spill (Full Name and Address) ᑭᖑᑦ ᑯᑎᑦᑎᑦ (ᐃᑎᑦ ᐊᒻᒪᓗ ᐳᕐᑎᕐᒃ)

Boart Longyear c/o Areva Resources

F Product(s) Spilled and Estimated Quantities (provide metric volumes/weights if possible) ᑭᖑᑦ ᑭᖑᓐᓂᑦ ᑯᐱᑦ ᑲᓄᑎᓗ ᐊᔪᓂᒃᑲᑦ (ᐊᔪᓂᖕᒐ ᐅᑭᔪᑦᓂᔪᑦᓐᓂᑦ ᐊᑦᓇᔪᑦ)

Radio Active Drill Cuttings 2 cubic meters Estimated

G Cause of Spill ᑭᖑ ᑯᐱᔪᑦᑕᑦ

Procedure to Collect and Bag Radio Active Drill Cutting not Followed

H Is Spill Terminated? ᑯᐱᔪᑦ ᓄᖃᑦᑕᑦ?	I If Spill is Continuing, Give Estimated Rate ᓱᓕ ᑯᐱᑦ ᑲᓄᑎᑦ ᓱᒃᑲᓕᑎᑦᑕᑯᑦ	J Is Further Spillage Possible? ᑯᐱᒃᓇᐅᐃᓐᓇᑭᐊᖃᑦ?	K Extent of Contaminated Area (in square metres if possible) ᑲᓄᑦ ᐊᔪᑎᑦᑕ ᑯᐱᐃᑦᑕᑦ (ᐅᑦᐅᔪᒪᓗᒍ ᐊᑦᓇᔪᑦᑕᑦ)
■ Yes/ᐃ ☐ No/ᐊᖃ	No	☐ Yes/ᐃ ■ No/ᐊᖃ	5-6 square meters

L Factors Affecting Spill or Recovery (weather conditions, terrain, snow cover, etc.) ᑭᖑ ᐱᔪᑦᑕᑦ ᑯᐱᔪᒥ ᐅᑦᑕᓗ ᐋᑭᑦᑕᐅᓇᓱᑎᑦᓗᒍ (ᓱᓕ ᑲᓄᐃᓕᖕᓂᖕᒐᓄᑦ, ᓄᓇ ᑲᓄᐃᓕᖕᓂᖕᒐᓄᑦ ᐊᐅᔾᔭᐅᓯᒪᓂᖕᒐᓄ, ᐊᓯᓐᓂᔾᔭᖕᑦᓗᒍ)

None

M Containment (natural depression, dykes, etc.) ᐅᑭᓯᐊᓗᖅᑐᐃᑦ ᑭᓕᐊᑦ ᐃᓱᖕᒐᓕᕐᓯᒪᔪᑦ (ᓄᓇᒥ ᐃᓱᖕᒐᐃᑦ, ᐊᓯᕐᓇᔾᔭᖕᑦᓗᒍ)

Natural depression

N Action, if any, taken or Proposed to Contain, Recover, Clean Up or Dispose of Product(s) and Contaminated Materials ᑲᓄᐃᓕᔾᔭᐅᑦ, ᑲᓄᐃᓕᔾᔭᐅᒥᐊᕐᑦ ᐅᑦᑕᓗ ᑲᓄᐃᓕᔾᔭᐅᒥᐊᕐᑦ ᐊᑕᐅᓯᕐᑎᑦᑕᐅᓇᓱᑦ, ᓄᖃᕐᑎᑦᑕᐅᓇᓱᑦ, ᓴᓗᒪᕐᓇᕐᑕᐅᑦ ᐅᑦᑕᓗ ᐃᑦᑕᐅᓂᐊᕐᑦ ᑯᐱᔪᑦ (ᑯᐱᔪᑦᓗᒃᑯᑦ) ᐊᒻᒪᓗ ᑯᐱᕐᐃᑦ.

Material being Collect and bagged and stored in Radioactive Storage Compound

O Do You Require Assistance? ᐃᑲᔪᑦᑕᐅᔭᓇᐊᖃᕐᐱᑦ? ■ No ᐊᖃ ☐ Yes, describe: ᐃ. ᓇᓗᓇᐃᔭᑦᓗᒍ

P Possible Hazards to Persons, Property or Environment e.g. fire, drinking water, fish or wildlife ᐋᑦᑕᓐᓇᐃᓐᓇᐊᖃᕐᑦ ᐃᓄᑦᓄᑦ, ᐱᖓᑎᔭᐅᔪᓄᑦ ᐅᑦᑕᓗ ᐊᑦᑎᒥ ᓱᓗ - ᐃᑭᑦᓂᓄ, ᐃᒥᑦᒥ ᓂᐅᖃᕐᑕᐅᓗᒍᑦᓂᓄ, ᐃᖃᓗᔪᓄᑦ ᐅᑦᑕᓗ ᓂᑦᔪᑎᓄᑦ

No Hazards

Q Comments and/or Recommendations ᐅᖃᐅᓂᓴᐃᑦ ᐊᒻᒪᓗ ᐅᑦᑕᓗᑦᓂᑦ ᑲᓄᐃᓕᑦᑕᖃᐅᔪᑦ

Procedure re-inforce with drilling contractor Spill Plan has been implemented. Area to be cleaned until site scan is below acceptable threshold.

FOR SPILL LINE USE ONLY
ᐊᑐᕐᑕᐅᔪᓐᓇᕐ ᑯᐱᔪᓄᑦ ᐅᖃᓚᐃᐅᑦᑐᓄᑐᐊᕐ

Lead Agency ᐃᖃᓄᐃᔭᕐᑐᓂᓴᐃᑦ ᑯᐱᔪᒥ ᑲᒪᒋᔭᖅᑐᑦ

Spill Significance ᑯᐱᔪᑦ ᑲᓄᐃᓕᖕᓂᖕᒐ

Lead Agency Contact and Time ᐃᖃᓄᐃᔭᕐᑐᓂᓴᐃᑦ ᑯᐱᔪᒥ ᑲᒪᒋᔭᖅᑐᑦ ᑮᐅᔾᒃᑲᕐᑕᐅᓂᖕᒐ ᐊᒻᒪᓗ ᑲᔪᓯᐊᕐᑎᑦᓗᒍ

Is this file now closed? ᑖᓐᓇ ᐅᓂᒃᑳᔭᐅᔪᕐ ᒪᔾᔭᐅᑦ?

Reported By ᐅᓂᒃᑳᖅᑐᑦ	Position, Employer, Location ᑲᓄᐃᑦᑐᒥ ᐃᖃᓄᐃᔭᓂᑦ, ᐃᖃᓄᐃᔭᕐᐱᖕᒐ, ᓇᑦ	Telephone ᐅᖃᓚᐅᑦ
Dan Zwitt	Site Supervisor Areva Resources Kiggavik Site Nunavut.	
Reported To ᐅᓂᐱᐅᔪᕐ	**Position, Employer, Location** ᑲᓄᐃᑦᑐᒥ ᐃᖃᓄᐃᔭᓂᑦ, ᐃᖃᓄᐃᔭᕐᑭᖕᒐ, ᓇᓂ	**Telephone** ᐅᖃᓚᐅᑦ