

**NUNAVUT SPILL REPORT** (Oil, Gas, Hazardous Chemicals or other Materials)

ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ (ᑎᓄᓐᓂᑦ, ᑎᓄᓐᓂᑦ, ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ)

24-Hour Report Line 24-ᓄᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ

Phone/ᑎᓄᓐᓂᑦ (867) 920-8130

Fax/ᑎᓄᓐᓂᑦ (867) 873-6924

A Report Date and Time ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ June 14, 2009 11:50 am		B Date and Time of Spill (if known) ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ June 13, 2009 Approx. 9:00 am		C ☐ Original Report ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ☒ Update No. 09 294 ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ		Spill Number ᑎᓄᓐᓂᑦ	
D Location and Map Coordinates (if known) and Direction (if moving) ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ UTM 14W 0565307 7146941							
E Party Responsible for Spill (Full Name and Address) ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ AREVA Resources Canada Inc. Box 9204-817-45th St. West, Saskatoon SK, S7K 3X5							
F Product(s) Spilled and Estimated Quantities (provide metric volumes/weights if possible) ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ Approximately 4 meters of core with a maximum of 1 meter of mineralized core.							
G Cause of Spill ᑎᓄᓐᓂᑦ Core boxes were being slung by a helicopter back to camp and was not properly secure. One box of core fell out of basket being used.							
H Is Spill Terminated? ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ☒ Yes/ᑎᓄᓐᓂᑦ ☐ No/ᑎᓄᓐᓂᑦ		I If Spill is Continuing, Give Estimated Rate ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ		J Is Further Spillage Possible? ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ☐ Yes/ᑎᓄᓐᓂᑦ ☒ No/ᑎᓄᓐᓂᑦ		K Extent of Contaminated Area (in square metres if possible) ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ Approx 3m ³	
L Factors Affecting Spill or Recovery (weather conditions, terrain, snow cover, etc.) ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ None				M Containment (natural depression, dikes, etc.) ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ This was solid material that was easily picked up and collected.			
N Action, if any, taken or Proposed to Contain, Recover, Clean Up or Dispose of Product(s) and Contaminated Materials ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ All core was picked up and put into a secure container and brought back to camp.							
O Do You Require Assistance? ☒ No ☐ Yes, describe: ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ				P Possible Hazards to Persons, Property or Environment e.g. fire, drinking water, fish or wildlife ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ None			
Q Comments and/or Recommendations ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ Actions have been taken to secure core boxes within the transport cage in order to prevent any future occurrences.						FOR SPILL LINE USE ONLY ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ Lead Agency ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ Spill Significance ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ Lead Agency Contact and Time ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ Is this file now closed? ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ	
Reported By ᑎᓄᓐᓂᑦ Kim Sarauer		Position, Employer, Location ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ Environment and Radiation Protection Supervisor, Kiggavik Project.				Telephone ᑎᓄᓐᓂᑦ (306) 683-9843	
Reported To ᑎᓄᓐᓂᑦ Terry		Position, Employer, Location ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ ᑎᓄᓐᓂᑦ Station operator, Spill line				Telephone ᑎᓄᓐᓂᑦ (867) 920-8130	