

NWB Annual Report

Year being reported: 2005



License No: NWB2KIR0507

Issued Date: September 15, 2005

Expiry Date: October 30, 2007

Project Name: Mountain and Dismal Lake Properties

Licensee: Triex Minerals Corporation

Mailing Address: P.O. Box 11584
1410 – 650 West Georgia Street
Vancouver, BC V6B 4N8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Same as above

General Background Information on the Project (*optional):

There were no workings undertaken in 2005. There were some day trips made to the property to begin centralizing garbage, debris and waste left behind by previous land users.

Licence Requirements: the licensee must provide the following information in accordance with

Part B



Item 2



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Domestic - unnamed lake adjacent to the camp	
Water Quantity:	5 cu.m	Quantity Allowable Domestic (cu.m)
	0	Actual Quantity Used Domestic (cu.m)
	N/A	Quantity Allowable Drilling (cu.m)
	N/A	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

Garbage and debris left by previous land users was centralized in 2005 ready for disposal.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

There were no spills.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

In 2005 Triex made day trips to the property to begin centralizing garbage, debris and waste that had been left by previous land users.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A) ▼

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A) ▼

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Triex Minerals is currently awaiting a water licence amendment which will allow for drilling to begin this upcoming field season, 2006.

Date Submitted:

March 30, 2006

Submitted/Prepared by:

Janet Stritychuk

Contact Information:

Tel: (604) 687-6644

Fax: (604) 687-1448

email: JStritychuk@diamondex.net