NWB Annual	Report	Year being reported: 2009 ▼
License No:	2BE-KIR0812	Issued Date: April 11, 2008 Expiry Date: October 31, 2012
		Expiry Bate: October 61, 2612
	Project Name:	KIRWAN LAKE PROJECT
	Licensee: TRIE)	K MINERALS CORPORATION
	Mailing Address:	PO BOX 11584 1410-650 W. GEORGIA ST., VANCOUVER, BC V6B 4N8
		filing Annual Report (if different from Name of Licensee please clarify e two entities, if applicable):
		Corporation. Canterra's predessesor company Diamondex with Triex Minerals and the new company was subsequently Minerals Corp.
General Back	kground Information	n on the Project (*optional):
Licence Require		see must provide the following information in accodance
	ter; sewage and gre	and waste disposal activities, including, but not limited to: methods of eywater management; drill waste management; solid and hazardous
	Water Source(s): Water Quantity:	No water usage in 2009 Quantity Allowable Domestic (cu.m) Actual Quantity Used Domestic (cu.m) Quantity Allowable Drilling (cu.m) Total Quantity Used Drilling (cu.m)

A list of unau	thorized discharges and a summary of follow-up actions taken.			
;	Spill No.: (as reported to the Spill Hot-line)			
	Date of Spill:			
	Date of Notification to an Inspector:			
, F	Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)			
	No unauthorized discharges occurred in 2009.			
Revisions to	the Spill Contingency Plan			
·	SCP submitted and approved - no revision required or proposed			
	Additional Details:			
ſ	There are no revisions to the Spill Contingency Plan.			
	and the second s			
L				
	the Abandonment and Restoration Plan			
-	AR plan submitted and approved - no revision required or proposed			
ŕ	Additional Details:			
Progressive F	Reclamation Work Undertaken			
	Additional Details (i.e., work completed and future works proposed)			
	The final clean-up and reclamation of the Kirwan lake exploration camp was			
	done between August 9 and 18, 2009. A clean-up report including photos is attached.			
Populte of the	e Monitoring Program including:			
nesults of the	e Monitoring Program including.			
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of			
(each location where sources of water are utilized;			
	Not Applicable (N/A)			
	Additional Details:			
	Water was not utilized in 2009 because the camp was not operational.			
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of			
•	each location where wastes associated with the licence are deposited;			
	Details described below			
	Additional Details:			
	Grey-water and latrine wastes are deposited in sumps and pits at co-ord's;			
	N67° 17' 53.1", W116° 52' 55.7" (Kirwan Lake camp location)			

	Results of any additional sampling and/or analysis that was requested by an Inspector		
	No additional sampling requested by an Inspector or the Board ▼		
	Additional Details: (date of request, analysis of results, data attached, etc)		
Any other de being reporte	tails on water use or waste disposal requested by the Board by November 1 of the year ed.		
	No additional sampling requested by an Inspector or the Board		
	Additional Details: (Attached or provided below)		
Any respons	es or follow-up actions on inspection/compliance reports		
	Inspection Report received by the Licensee (Date): ▼		
,	Additional Details: (Dates of Report, Follow-up by the Licensee)		
	INAC Inspection Report received Nov. 30, 2009. Inspection date July 29, 2009. Licensee cleaned up the Kirwan Lake site during period August 9 to 18, 2009. Final Camp clean-up report submitted by licensee Sept. 3, 2009.		
Any addition	al comments or information for the Board to consider		
	Two additional areas subject to Water License 2BEKIR0812 and LUP N2005C0023 namely, Hope Lake Staging Area and Esker Airstrip require clean-up and restoration. These sites are scheduled for clean-up during the summer of 2012.		
Date Submitted: Submitted/Prepared by: Contact Information: Tel: 604-687-6644 Fax: 604-687-1448 email: wmelnyk@canterraminerals.com			