

NWB Annual Report

Year being reported: 2020

License No: 2BE-LUX2025 **Issued Date:** July 13, 2020
Expiry Date: October 31, 2025

Project Name: Luxx Project

Licensee: North Arrow Minerals Inc.

Mailing Address:
 Suite 960 - 789 West Pender Street
 Vancouver, BC
 V6C 1H2

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

n/a

General Background Information on the Project (*optional):

Work has not been conducted at the Luxx Project since 2014.

Licence Requirements: the licensee must provide the following information in accordance with

Select ▼ Select ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	n/a	
Water Quantity:	0	Quantity Allowable Domestic (cu.m)
	0	Actual Quantity Used Domestic (cu.m)
	0	Quantity Allowable Drilling (cu.m)
	0	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
- ☐ Sewage
- ☐ Drill Waste
- ☐ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

There was no work conducted on the property in 2020

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

There was no work conducted on the property in 2020

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

n/a

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

n/a

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

n/a

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A) ▼

Additional Details:

There was no work conducted on the property in 2020

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A) ▼

Additional Details:

There was no work conducted on the property in 2020

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

There was no work conducted on the property in 2020

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

There was no work conducted on the property in 2020

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

n/a

Any additional comments or information for the Board to consider

n/a

Date Submitted:

Mar. 2, 2021

Submitted/Prepared by:

Mike MacMorran, Geologist North Arrow Minerals

Contact Information:

Tel: 604-563-4808

Fax:

email: mmacmorran@northarrowminerals.com