NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE
TEL: (867) 920-8130
FAX: (867) 873-6924
EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR **01-11-2024**	REPORT TIME **8:00**	X ORIGINAL SPILL REPORT, OR ☐ UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER ____-_____
B	OCCURRENCE DATE: MONTH – DAY – YEAR **01-10-2024**	OCCURRENCE TIME **15:00**		
C	LAND USE PERMIT NUMBER (IF APPLICABLE) **KVPL11D01**	WATER LICENCE NUMBER (IF APPLICABLE) **2BB-MEL-1424**		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION **Meliadine Gold Mine**	REGION ☐ NWT X NUNAVUT ☐ ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES **63** MINUTES **2** SECONDS **21**	LONGITUDE DEGREES **92** MINUTES **13** SECONDS **41**		
F	RESPONSIBLE PARTY OR VESSEL NAME **Agnico Eagle Mines Ltd.**	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION **Meliadine, Rankin Inlet, Nunavut, X0C 0G0**		
G	ANY CONTRACTOR INVOLVED **N/A**	CONTRACTOR ADDRESS OR OFFICE LOCATION **Meliadine, Rankin Inlet, Nunavut, X0C 0G0**		
H	PRODUCT SPILLED **Sewage**	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES **1m3**	U.N. NUMBER **N/A**	
	SECOND PRODUCT SPILLED (IF APPLICABLE) **N/A**	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES **N/A**	U.N. NUMBER **N/A**	
I	SPILL SOURCE **Exploration camp lift station**	SPILL CAUSE **Overflow at lift station**	AREA OF CONTAMINATION IN SQUARE METRES **Unknown**	
J	FACTORS AFFECTING SPILL OR RECOVERY **Infrastructure**	DESCRIBE ANY ASSISTANCE REQUIRED **N/A**	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT **N/A**	

K ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS

Approximately 1m3 of sewage spilled from the Exploration Camp sewage lift station tank. The spill was contained to the local area. Clean-up activities are ongoing.

The coordinates of the spill are 63° 1' 44.39'' N, 92° 10' 11.01'' W. No water bodies were impacted by this spill. The nearest natural water body (Meliadine Lake) is 100 m southeast.

Pursuant to Part H, Item 4c of water license 2BB-MEL-1424, a follow-up report will be issued after the investigation is completed.

Reported by Spencer Knowles Environment Technician, 819-759-3555 x4603903 spencer.knowles@agnicoeagle.com.

L	REPORTED TO SPILL LINE BY **Spencer Knowles**	POSITION **Env. Technician**	EMPLOYER **AEM**	LOCATION CALLING FROM **Meliadine**	TELEPHONE **819-759-3555**
M	ANY ALTERNATE CONTACT **Sara Savoie**	POSITION **Env. Superintendent**	EMPLOYER **AEM**	ALTERNATE CONTACT LOCATION **Meliadine**	ALTERNATE TELEPHONE **819-856-9349**

REPORT LINE USE ONLY

N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130

LEAD AGENCY ☐ EC ☐ CCG ☐ GNWT ☐ GN ☐ ILA ☐ INAC ☐ NEB ☐ TC | SIGNIFICANCE ☐ MINOR ☐ MAJOR ☐ UNKNOWN | FILE STATUS ☐ OPEN ☐ CLOSED

AGENCY	CONTACT NAME	CONTACT TIME	REMARKS
LEAD AGENCY			
FIRST SUPPORT AGENCY			
SECOND SUPPORT AGENCY			
THIRD SUPPORT AGENCY			