

WATER USE INSPECTION REPORT

Date: August 2 nd , 2008	Licensee Rep. (Name/Title): Roger March & Kevin Fowler	
Licensee: Meliadine Resources Ltd.		Licence No: 2BE-MEP0813

WATER SUPPLY

Source(s): Atulik Lake.	Quantity used: – Records noted
Owner:/Operator: Riverside Geoscience Inc.	Camp and drill Operations

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Intake Facilities: NI	Storage Structure: A	Treatment Sys: NA	Chemical Storage: NA
Flow Meas. Device: NA	Conveyance Lines: NA	Pumping Stations: NA	Screen : NA

Comments: Water for the exploration camp is -treated with UV and Filtration at the Exploration Camp. The Water intake pump is not metered and this must be addressed by the next Inspection.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec./Ter.): Incineration

Natural Water Body: NA	Continuous Discharge (land or water):NA	
Seasonal Discharge: NA	Wetlands Treatment: NA	Trench: NA

Comments: Incinerator noted on site.

Solid Waste:

Landfill: NA	Burn & Landfill: NA	Other: historic wastes being addressed
---------------------	--------------------------------	---

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Discharge Quality: NA	Decant Structure: NA	Erosion: A
Discharge Meas. Device: NA	Dyke Inspection: NA	Seepages: A
Dams, Dykes: NI	Freeboard: A	Spills: NA
Construction: NI	O&M Plan: NI	A&R Plan: NI
Periods of Discharge: NA.	Effluent Discharge Rate: NA	

Comments: An Incinerator is on site. Hazardous wastes are back hauled to Baker Lake. Pre-existing camp infrastructure, old drill materials, drums etc, removed under a progressive reclamation program.

FUEL STORAGE:.

Waste Oil Storage: None noted

Owner/Operator: Meliadine Resources Ltd

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Berms & Liners: NA	Water within Berms: NA	Evidence of Leaks: NA
Drainage Pipes: NA	Pump Station & Catchments Berm: NA	
Pipeline Condition: NA	Condition of Tanks: NA	

Comments: Secondary Containment was not noted at the camp. This should be addressed before the next inspection.

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected : 0		Owner /Operator: Meliadine Resources Ltd .	
Samples Collected : 1		INAC: Potable	
Signs Posted	SNP: None	Warning: U	
Records & Reporting: Annual reporting must be filed by march 31 st 2009			
Geotechnical Inspection: N/A			

Non-Compliance of Act or Licence: The Camp is being cleaned up. Previous use at this location has left a stockpile of old drill equipment, drums and old buildings. The camp location is sound but snow may be an issue. The Inspector did not note any issues at this time.

A.Keim

Inspector's Name

Sent by E-mail

Inspector's Signature