



INDUSTRIAL WATER USE INSPECTION REPORT

DATE: July 09, 2012

COMPANY REP.: _____

LICENSEE: Agnico Eagle Mines

LICENCE #: 2BE-MEPOS13

WATER SUPPLY

Source: Atulik Quantity Used: Unknown Meter Rdg.: _____

Indicate: **A - Acceptable**

U - Unacceptable

N/A - Not Applicable

Intake Facilities	<u>NA</u>	Storage Structures	<u>NA</u>	Treatment Systems	<u>NA</u>	Recycling	<u>NA</u>
Flow Meas. Device	<u>NA</u>	Conveyance Lines	<u>NA</u>	Pumping Stations	<u>NA</u>	Modifications	<u>NA</u>

Comments: Site is inactive, this site was decommissioned
Therefore no water was being used

WASTE DISPOSAL

Tailings: Tailings Pond ☐ Natural Lake ☐ Underground ☐

Sewage: Sewage Treat. System ☐ Tailings Pond ☐ Natural Water Body ☐
Continuous Discharge ☐ Inter. Dischg. ☐

Solid Waste: Open Dump ☐ Landfill ☐ Burn & Bury ☐ Underground ☐

Indicate: **A - Acceptable**

U - Unacceptable

N/A - Not Applicable

Discharge Quality	<u>NI</u>	Conveyance Lines	<u>NA</u>	Disch. Meas. Dev.	<u>NA</u>	Freeboard	<u>NA</u>
Decant Structures	<u>NA</u>	Pond Treatment	<u>NA</u>	Dams, Dykes	<u>NA</u>	Seepages	<u>NA</u>
Dyke Inspections	<u>NA</u>	Runoff Diversion	<u>NA</u>	Erosion	<u>NA</u>	Spills	<u>NA</u>

Effluent Discharge Rate: _____ Samples Collected: No samples collected

Comments: Site is inactive, No fuel was noted onsite

- The site was tidy
- No grey water produced

GENERAL CONDITIONS

Indicate: **A - Acceptable**

U - Unacceptable

N/A - Not Applicable

Ore & Waste Rock Stockpiles	<u>NA</u>	Records & Reporting	<u>NI</u>	Surv. Net. Prog.	<u>NI</u>
Geotechnical Inspection	<u>NA</u>	Posting, Signage	<u>NI</u>	Contingency Plan	<u>NA</u>
Restoration Activities	<u>NA</u>	New Construction	<u>NA</u>	Fuel Storage	<u>NA</u>
Mine Water Discharge	<u>NA</u>	Chemical Storage	<u>NI</u>	Annual Report	<u>A</u>

Comments: License expires on October 31, 2012 2013

- Updated A&M requirements are to be submitted (A&R, O&M, Spill plan)

Violations of Act or Licence: No issues identified

General Comments: 6 building are still erect on site, walking
Path ways have been lifted from ground and removed

- Drilling equipment still on site
- All building should be deconstructed and backhauled as well as other camp materials

Page 2 attached ☐ Yes ☐ No

Licensee Representative's Title _____

Inspector's Name _____

Licensee Representative's Signature _____

Inspector's Signature _____