

NWB Annual Report

Year being reported:

2016

License No: 2BE-MEP1318

Issued Date:

June 27, 2013

Expiry Date:

October 31, 2018

Project Name: Meliadine East Project

Licensee: Agnico Eagle Mines Ltd.

Mailing Address: C.P. 87, 765 chemin de la mine Goldex  
Val-d'Or, Qc  
J9P4N9

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (\*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B

▼ Item 2 ▼

**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.**

Water Source(s):	Local lakes and ponds		
Water Quantity:	10m <sup>3</sup> /day	Quantity Allowable Domestic	
	0	Actual Quantity Used Domestic (cu.m)	
	289m <sup>3</sup> /day	Quantity Allowable Drilling (cu.m)	
	0	Total Quantity Used Drilling	

Waste Management and/or Disposal

- ☐ Solid Waste Disposal  
☐ Sewage  
☐ Drill Waste  
☐ Greywater  
☐ Hazardous  
☐ Other:

Additional Details:

No activities were conducted under this license in 2016.

**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No unauthorized discharge in 2016.

### Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

### Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

No activities were conducted under this license in 2016.

### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Not Applicable (N/A)



Additional Details:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Not Applicable (N/A)



Additional Details:

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

**Any additional comments or information for the Board to consider**

**Date Submitted:**

November 29, 2016

**Submitted/Prepared by:**

David Frenette

**Contact Information:**

**Tel:** 819.874.5980 ext. 3622

**Fax:**

**email:** [david.frenette@agnicoeagle.com](mailto:david.frenette@agnicoeagle.com)