

## NWB Annual Report

Year being reported:

Select ▼

License No: 2BE-MLL1217

Issued Date: March 27, 2012

Expiry Date: March 26, 2017

Project Name: WISHBONE MALLEY

Licensee: SABINA GOLD AND SILVER CORP.

Mailing Address: Suite 375, Two Bentall Centre,  
555 Burrard St., Box 220  
Vancouver, BC. V7X 1M7

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

SABINA GOLD AND SILVER CORP.

## General Background Information on the Project (\*optional):

Located approximately 50 km's west of Sabina's Back River Project.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼

Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Water Quantity:

45m3

N/A

130m3

N/A

Quantity Allowable Domestic (cu.m)

Actual Quantity Used Domestic (cu.m)

Quantity Allowable Drilling (cu.m)

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☐ Solid Waste Disposal☐ Sewage☐ Drill Waste☐ Greywater☐ Hazardous☐ Other:

Additional Details:

No activities occurred within the Wishbone Malley licence boundaries. No water use or waste disposal occurred.

**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

N/A

**Revisions to the Spill Contingency Plan**

SCP submitted and approved - no revision required or proposed



Additional Details:

**Revisions to the Abandonment and Restoration Plan**

AR plan submitted and approved - no revision required or proposed



Additional Details:

**Progressive Reclamation Work Undertaken**

Additional Details (i.e., work completed and future works proposed)

No activities occurred.

**Results of the Monitoring Program including:**

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Not Applicable (N/A)



Additional Details:

No monitoring as per conditions of the water licence occurred.

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Not Applicable (N/A)



Additional Details:

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

**Any additional comments or information for the Board to consider**

**Date Submitted:**

March 31, 2016

**Submitted/Prepared by:**

John Laitin

**Contact Information:**

**Tel:** 604 998 4175

**Fax:** 604 998 1051

**email:** [jlaitin@sabinagoldsilver.com](mailto:jlaitin@sabinagoldsilver.com)