

NWB Annual Report

Year being reported:

Select



License No: 2BE-MLL1722

Issued Date: June 30, 2017

Expiry Date: June 29, 2022

Project Name: Wishbone-Malley Project

Licensee: SABINA GOLD AND SILVER CORP

Mailing Address: #1800 - 555 Burrard Street, Box 220, Vancouver, BC,
V7X 1M7

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

SABINA GOLD AND SILVER CORP

General Background Information on the Project (*optional):

Located approximately 50 km west of Sabina's Back River Project.

Licence Requirements: the licensee must provide the following information in accordance with

Part B



Item 2



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	N/A	
Water Quantity:	70	Quantity Allowable Domestic (cu.m)
		Actual Quantity Used Domestic (cu.m)
	130	Quantity Allowable Drilling (cu.m)
		Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

Wishbone-Malley was not operational in 2019. No water use or waste disposal occurred.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

N/A

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

Submitted June 2018

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

Submitted March 2017

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Progressive reclamation were not undertaken.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A) ▼

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A) ▼

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:

Apr-20

Submitted/Prepared by:

Merle Keefe

Contact Information:

Tel:

Fax:

email: mkeefe@sabinagoldsilver.com