NWB Annual Report		Year being reported: 2009					
License No: 2BE-MSX0712 Issued Date: May 16, 2007							
		Expiry Date: May 31, 2012					
	Project Name:	Muskox Project					
	Licensee: Silver	met Inc.					
	Mailing Address:	8 King Street East, Suite 1700 Toronto ON M5C 1B5					
		l resemble an initial and					
	Name of Company f	illing Annual Poport (it different from Name of Linear Plants					
	Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):						
General Bac	General Background Information on the Project (*optional):						
	There was no activity in 2009						
	Licence Requirements: the licensee must provide the following information in accodance						
with	Part B 🔻 Ite	em 2					
A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.							
	Water Source(s):	Silvermet Lake (camp) - no activity					
	Water Quantity:	included below Quantity Allowable Domestic (cu.m)					
		none Actual Quantity Used Domestic (cu.m) 18 cu m/day Quantity Allowable Drilling (cu.m)					
		none Total Quantity Used Drilling (cu.m)					
	Waste Management a Solid Waste Dis Sewage Drill Waste						
	Greywater						
	Hazardous Other:						
	Additional Details:						
	No activity in 2009						

A list of unau	thorized discharges and a summary of follow-up actions taken.					
	Spill No.: None (as reported to the Spill Hot-line)					
	Date of Spill:					
	Date of Notification to an Inspector:					
	Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)					
ı						
Į	See attached notes on waste management relating to drill cuttings issue.					
Revisions to	the Spill Contingency Plan					
rtorioiono to	N/A - not applicable					
	THE THE OPPOSITION					
	Additional Details:					
Povisions to	the Abandonment and Restoration Plan					
Revisions to						
	No Abandonment and Restoration (AR) Plan submitted or approved					
	Additional Details:					
1						
Į						
	Reclamation Work Undertaken					
	Additional Details (i.e., work completed and future works proposed)					
Results of the	e Monitoring Program including:					
	- mentering of egents motuating.					
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of					
	each location where sources of water are utilized;					
	Details described below					
	Additional Details:					
ı	O N. 0.0					
	Camp - N 66 degrees 59' 9.7" and W 114 degrees 53' 51.4"					
l						
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of					
	each location where wastes associated with the licence are deposited;					
	Details described below					

Additional De	etails:				
Results of a	ny additional sampling and/or analysis that was requested b	by an Inspector			
No additional sa	ampling requested by an Inspector or the Board	V			
Additional De	etails: (date of request, analysis of results, data attached, etc)				
	er use or waste disposal requested by the Board by Novembe	er 1 of the year			
being reported. No additional sa	ampling requested by an Inspector or the Board	V			
(100 - 101 - 100 - 101 -	etails: (Attached or provided below)				
Any responses or follow-	up actions on inspection/compliance reports				
Select		~			
Additional De	Additional Details: (Dates of Report, Follow-up by the Licensee)				
Subsequent	closure plans submitted				
Any additional comments	or information for the Board to consider				
Date Submitted: Submitted/Prepared by: Contact Information:	May 2, 2005 Rein Lehari Tel: 416-203-8336 Fax: 416-368-5146				
	Fax: 416-368-5146 email: rlehari@silvermet.ca				