

NWB Annual Report

Year being reported: 2010 ▼

License No: 2BE-MSX0712 Issued Date: May 16, 2007
 Expiry Date: December 31, 2012

Project Name: Muskox Project

Licensee: Silvermet Inc.

Mailing Address: 8 King Street East, Suite 1700
 Toronto ON M5C 1B5

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

There was no activity during 2010

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Silvermet camp and drilling locations - no activity in 2010	
Water Quantity:	included below	Quantity Allowable Domestic (cu.m)
	none	Actual Quantity Used Domestic (cu.m)
	18 cu m/day	Quantity Allowable Drilling (cu.m)
	none	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

No waste disposal occurred during 2010

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

Additional Details:

Revisions to the Abandonment and Restoration Plan

Additional Details:

- Abandonment & restoration plan was submitted to INAC by Aurora Geosciences on behalf of Silvermet on February 25, 2010
- INAC responded on April 8, 2010, taking issue with the proposed burning of wood products at the camp site
- Aurora Geosciences made further submissions about the proposed wood burning

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Additional Details:

Drill locations previously reported (2007 report)

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Additional Details:

Camp - N 66 degrees 59'9.7" and W 114 degrees 53'51.4

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Inspection Report received by the Licensee (Date):

Additional Details: (Dates of Report, Follow-up by the Licensee)

A water use inspection report dated July 28, 2010 was received from INAC, identifying that the camp had not been removed, a fuel cache remained and debris remained at a drill laydown area. Silvermet determined that progress was not being made adequately by Aurora Geosciences on the clean-up and beginning at the end of the year, Silvermet took direct control over this process (see 2011 report)

Any additional comments or information for the Board to consider

Date Submitted:

June 24, 2014

Submitted/Prepared by:

Rein Lehari

Contact Information:

Tel: 416-203-8336

Fax:	416-368-5146
email:	rlehari@silvermet.ca

