



ENVIRONMENTAL INSPECTION FORM

☒ Original

☐ Follow-Up Report

Licensee		Licensee Representative	
Vale Exploration Canada Inc.		Clayton Pearson	
Licence No. / Expiry		Representative's Title	
2BE-MVP1217		Project Geologist	
Land / Other Authorizations		Land / Other Authorizations	
N2012C0008			
Date of Inspection		Inspector	
15/07/2014		Atuat Shouldice	
Activities Inspected			
<div><input checked="" type="checkbox"/> Camp<div><input type="checkbox"/> Roads/Hauling</div></div> <div><input type="checkbox"/> Drilling<div><input type="checkbox"/> Other: Water Discharge</div></div> <div><input type="checkbox"/> Mining</div> <div><input type="checkbox"/> Construction<div><input type="checkbox"/> Other:</div></div> <div><input checked="" type="checkbox"/> Reclamation</div> <div><input checked="" type="checkbox"/> Fuel Storage</div>			

Conditions:    **A - Acceptable**    **C - Concern**    **U - Unacceptable**    **NA – Not Applicable**    **NI – Not Inspected**

Water Use			Site Conditions			Haz/Mat Management		
	Condition	Comment		Condition	Comment		Condition	Comment
Intake/Screen	N/A		Water Management Structures	N/A		Storage	N/A	
Flow Measure. Device	N/A		Culverts / Bridges	N/A		Spills	N/A	
Source:	N/A		Drainage	N/A		Spill Plan	N/A	
Water Use:	N/A		Erosion / Sediment	A				
Recirculation ( y /n)	NA		Mitigation Measures	A		Administrative		
			Reclamation Activities	N/A		Records	N/I	
			Materials Storage	N/A		Reports	N/I	
Waste Disposal			Signage	N/A		Plans	N/I	
Waste Water	A					Notifications	N/I	
Solid Waste	A		Monitoring			Other		
Hazardous Waste	A		Sample Collection / Analysis	N/A				

*\*The number in the comments field will correspond with specific comments provided below.*

Samples taken by Inspector:	Location(s):
<div><input type="checkbox"/> Yes   <input checked="" type="checkbox"/> No</div>	<ul style="list-style-type: none"><li>Camp- N68 20' 23.0" W85 44' 43.3"</li><li>Cache 1 N68  20' 19.0" W85 44' 46.0"</li><li>Cache 2 N68 29' 19.0" W85 44' 53.0"</li><li>Cache 3 N68 20' 30.0" W85 44' 41.0"</li></ul>

SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
-----------	----------------------------------------------	-------------------------------------------------------------	------------------------------------------

Background

Vale Exploration Canada Inc. had applied for closure of land use permit N2012C0008 and cancellation of water licence 2BE-MVP1217 in 2014, a final inspection was conducted on July 15<sup>th</sup> 2014 by inspector Atuat Shouldice and inspector Robert Savard. The area has been well used in the past; adjacent to where Vale exploration had their exploration camp is Cam-5 and West Melvillie’s east camp.

Inspectors Statement

Sites inspected are listed below.

- Camp- N68 20' 23.0" W85 44' 43.3"
- Cache 1- N68  20' 19.0" W85 44' 46.0"
- Cache 2- N68 29' 19.0" W85 44' 53.0"
- Cache 3- N68 20' 30.0" W85 44' 41.0"



SECTION 2

☒ Comments

☐ Non-Compliance with Act or Licence

☐ Action Required

Vale Exploration Canada Inc. left the area clean and tidy and in a natural state as required in the permit conditions prior to closure.  
Vale Explorations removed all equipment from the site and there was no evidence of ash, product stains or garbage in the areas of activity listened above.

Inspector Recommends Closure for land use permit N2012C0008

Inspector recommends cancellation for water licence 2BE-MVP1217

Inspector's Name

Atuat Shouldice

Signature

Date

September 25<sup>th</sup> 2014

Inspector's Name

Erik Allain

Signature

Date

3 Oct, 2014

Office Use Only: Follow-up report to be issued by Inspector

☐ Yes ☒ No