

NWB Annual Report

Year being reported:

2019

License No: 2BE-NAD1722 Issued Date: July 18, 2017
 Expiry Date: July 17, 2022

Project Name: Dewar Lakes Camp - Baffin Gold Project

Licensee: Commander Resources Ltd.

Mailing Address: 1111 Melville Street
 Vancouver, BC, V6B 3V6

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Tara Gunson, APEX Geoscience Ltd. (contractor assisting with permitting)

General Background Information on the Project (*optional):

The Baffin Island Project is a gold exploration project located in the Qikiqtani Region of Nunavut. Valore Metals Corporation (formerly Kivalliq Energy Corporation) utilized Commander's Dewar Lakes Camp to operate their 2017 & 2018 exploration program but did not have a field program at the Property in 2019.

Licence Requirements: the licensee must provide the following information in accordance with

Part B Item 2

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Dewar River	
Water Quantity:	2	Quantity Allowable Domestic (cu.m)
	0	Actual Quantity Used Domestic (cu.m)
	0	Quantity Allowable Drilling (cu.m)
	0	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

There was no waste produced at the Project in 2019.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)
 Date of Spill:
 Date of Notification to an Inspector:
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

There were no spills at the Project in 2019.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

The Spill Prevention and Response Plan was updated and submitted in 2017. No further changes have been made.

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

The Abandonment and Restoration Plan was updated and submitted in 2017. No further changes have been made.

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

No reclamation occurred at the Project in 2019.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below ▼

Additional Details:

Camp water was sourced from the Dewar River at 68°37'58" latitude, 71°6'32" longitude in 2017 and 2018. No water was used at the Project in 2019.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below ▼

Additional Details:

The camp incinerator was located at 68°37'59" latitude, 71°6'40" longitude. The incinerator was not used at the Project in 2019.

incinerator was not used at the Project in 2019.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

No inspections were conducted at the Project in 2019.

Date Submitted:	2020-03-24						
Submitted/Prepared by:	Tara Gunson						
Contact Information:	<table border="1"> <tr> <td>Tel:</td> <td>(780) 467-3532</td> </tr> <tr> <td>Fax:</td> <td>(780) 467-4025</td> </tr> <tr> <td>email:</td> <td>tgunson@apexgeoscience.com</td> </tr> </table>	Tel:	(780) 467-3532	Fax:	(780) 467-4025	email:	tgunson@apexgeoscience.com
Tel:	(780) 467-3532						
Fax:	(780) 467-4025						
email:	tgunson@apexgeoscience.com						