

**PEREGRINE DIAMONDS LTD.
NANUQ PROJECT PHOTOS AND MAP – 2012**

PHOTOS



**TOP: View from bear-fence south gate toward closed camp during Peregrine visit – 18 August 2012.
ABOVE: Interior of empty kitchen (tent skin removed) – 18 August 2012.**



TOP: Drill-equipment laydown area after demobe – 20 August 2012. (LY-38 drill was removed in 2011.)
ABOVE: Boart Longyear fuel tanks and pump tray on natural airstrip just prior to demobe – 19 August 2012.



Looking E across covered tent-drum berms behind camp – 18 August 2012.



Inciner8 B-60 in foreground; old spare incinerator in background -- 18 August 2012.



One of two outhouse shacks was found blown over during Peregrine site inspection; pits were covered -- 18 August 2012.



Petrol and tent drums in berm in foreground; diesel berm in background -- 18 August 2012.




Aviation-fuel berm with spill kits at camp -- 18 August 2012.



Propane and komatik storage -- 18 August 2012.

MAP



Nanuq Camp remained unchanged in 2012 and no programme was conducted in 2012.