

NWB Annual Report

Year being reported:

2017

License No: 2BE-NAN1318

Issued Date:

January 18, 2013

Expiry Date:

June 30, 2018

Project Name:

Nanuq

Licensee:

Peregrine Exploration Ltd.

Mailing Address:

Suite 654 - 999 Canada Place  
Vancouver, British Columbia  
Canada V6C 3E1

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Peregrine Exploration Ltd.

General Background Information on the Project (\*optional):

No field work was conducted in 2017. Located on NTS 56G03.

Licence Requirements: the licensee must provide the following information in accordance with

Part B



Item 2



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Lorillard River

Water Quantity:

10 per day

Quantity Allowable Domestic (cu.m)

0 per day

Actual Quantity Used Domestic (cu.m)

50 per day

Quantity Allowable Drilling (cu.m)

0

Total Quantity Used Drilling (cu.m)

Total Water Used = 13 days x 0.025m<sup>3</sup>/day = 0.0325 m<sup>3</sup>

Waste Management and/or Disposal

☐ Solid Waste Disposal

☐ Sewage

☐ Drill Waste

☐ Greywater

☐ Hazardous

☐ Other:

Additional Details:

No field work conducted in 2017.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No Spills in 2017.

### Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

No revisions

### Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

No revisions

### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

No field work conducted in 2017.

### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Details described below ▼

Additional Details:

WGS 84:  
Latitude 65 degrees, 13'43.62"N (WGS84)  
Longitude 91 degrees, 05'20.04"W (WGS84)

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Not Applicable (N/A) ▼

Additional Details:

Nanuq Camp - Outhouse,  
Latitude 65 degrees, 13' 43"N (WGS84)  
Longitude 91 degrees, 05' 25"W (WGS84)

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

No additional sampling requested.

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

No additional sampling requested.

**Any responses or follow-up actions on inspection/compliance reports**

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Inspection completed by RMO Christine Wilson July 2017. Questions regarding the ownership of 2 fuel drums in on a sand airstip 1.5 km SE of Nanuq Camp. Peregrine will investigate in 2018.

**Any additional comments or information for the Board to consider**

**Date Submitted:**

February 1, 2018

**Submitted/Prepared by:**

David Willis

**Contact Information:**

**Tel:** 604-608-4524

**Fax:** 604-408-8881

**email:** [dave@pdiam.com](mailto:dave@pdiam.com)