

NWB Annual Report

Year being reported: 2021

License No: 2BE-NAN1823 Issued Date: August 24, 2018
Expiry Date: August 23, 2023

Project Name: Nanuq

Licensee: Peregrine Diamonds Ltd.

Mailing Address: C/O De Beers Group
Suite 300, 1601 Airport Road NE
Calgary, Alberta
T2E 6Z8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Peregrine Diamonds Ltd. a subsidiary of De Beers Canada Inc.

General Background Information on the Project (*optional):

No field work was conducted in 2021. Camp located on 1:50,000 NTS 56G03.

Licence Requirements: the licensee must provide the following information in accordance with

Part B Item 2

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s): Lorillard River
Water Quantity: 10 per day Quantity Allowable Domestic (cu.m)
0 per day Actual Quantity Used Domestic (cu.m)
50 per day Quantity Allowable Drilling (cu.m)
0 Total Quantity Used Drilling (cu.m)
Total Water Used 2019 = 0 days x 0.00m3/day = 0.00 m3

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

No field work conducted in 2021.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No Spills in 2021.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

No revisions

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed

Additional Details:

No revisions

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

No field work conducted in 2021.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below

Additional Details:

WGS 84:
Latitude 65 degrees, 13'43.62"N (WGS84)
Longitude 91 degrees, 05'20.04"W (WGS84)

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A)

Additional Details:

Nanuq Camp - Outhouse,
Latitude 65 degrees, 13' 43"N (WGS84)
Longitude 91 degrees, 05' 25"W (WGS84)

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

No additional sampling requested.

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

No additional sampling requested.

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC



Additional Details: (Dates of Report, Follow-up by the Licensee)

No CIRNAC inspections in 2021.

Any additional comments or information for the Board to consider

Peregrine does not have any fuel drums stored at the Nanuq Camp, the natural airstrips in close proximity to the Nanuq Camp or the project area.

Date Submitted:

February 07,2022

Submitted/Prepared by:

David Willis

Contact Information:

Tel: 604-836-3284

Fax:

email: David.Willis@debeersgroup.com