

NWB Annual Report

Year being reported:

Select ▼ 2013.

License No:

2BE-NQNO914  
NA

Issued Date:

JUN. 18, 2009

Expiry Date:

OCT. 31, 2014

Project Name:

VANCO NORTH

Licensee:

PEREGRINE DIAMONDS LTD.

Mailing Address:

SUITE 201 - 1250 HOMER ST.  
VANCOUVER, B.C.  
V6B-1C6.

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

PEREGRINE DIAMONDS LTD.

General Background Information on the Project (\*optional):

PROJECT INITIATED IN 2009, NO PREVIOUS PERMIT  
2BE-NQNO914

Licence Requirements: the licensee must provide the following information in accordance with

Select B ▼ Select 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

UNNAMED LAKE

Water Quantity:

8/Day

Quantity Allowable Domestic (cu.m)

0

Actual Quantity Used Domestic (cu.m)

50/Day

Quantity Allowable Drilling (cu.m)

0

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☒ Solid Waste Disposal

☒ Sewage

☒ Drill Waste

☒ Greywater

☒ Hazardous

☒ Other:

Additional Details:

NO WORK DONE, NO WASTE GENERATED.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

*No SPILLS.*

#### Revisions to the Spill Contingency Plan

Select  ▼

Additional Details:

*No REVISIONS*

#### Revisions to the Abandonment and Restoration Plan

Select  ▼

Additional Details:

*No REVISIONS*

#### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

*No RECLAMATION DONE OR NECESSARY*

#### Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Select  ▼

Additional Details:

*No WATER UTILIZED IN 2013*

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Select  ▼

Additional Details:

*No WASTE GENERATED IN 2013.*

## Results of any additional sampling and/or analysis that was requested by an Inspector

Select *No ADDITIONAL SAMPLING REQUESTED* ▼

Additional Details: (date of request, analysis of results, data attached, etc)

*No ADDITIONAL SAMPLING*

## Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

Select *No ADDITIONAL SAMPLING REQUESTED* ▼

Additional Details: (Attached or provided below)

*No OTHER DETAILS*

## Any responses or follow-up actions on inspection/compliance reports

Select *No INSPECTION OR COMPLIANCE Rpt. ISSUED* ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

*No INSPECTIONS CONDUCTED*

## Any additional comments or information for the Board to consider

*No work DONE in 2013*

Date Submitted:

*Nov. 28, 2013*

Submitted/Prepared by:

*DAVID WILLIS*

Contact Information:

Tel:

*Home : 609-608-7527*

Fax:

*609-708-8881*

email:

*davecpdian.com*