


Water Licence Inspection Report

☒Original

☐Follow-Up Report

Authorization	Representative
2BE-NUE1318	Uru Metals Ltd.
Authorization No. / Expiry	Representative's Title
August 29, 2018	NA
Inspection Date	Inspector
August 21, 2025	RMO Kyle Amsel
Other Authorization/s	
N2008C0006	
Activities Inspected	
<input type="checkbox"/> Municipal <input type="checkbox"/> Camp, Commercial <input checked="" type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input checked="" type="checkbox"/> Fuel Storage <input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Winter Hauling <input type="checkbox"/> Camp, Private <input type="checkbox"/> Other Click or tap here to enter text.	

Section 1 Comments
<p>On August 21, 2025 Resource Management Officer Kyle Amsel (Inspector) for Crown-Indigenous Relations and Northern Affairs Canada conducted an Inspection of Water Licence 2BE-NUE1318 (Licence) Issued to Uru Metal Ltd. (Licensee) for use of water and deposit of waste in support of and exploration undertaking (undertaking).</p> <p>No representative was on site for inspection. No camp was established as part of this authorization.</p> <p>Preliminary Information</p> <p>The noted licence had no camp established with it. Records indicate the associated Land Use Permit received final inspection in 2013.</p> <p>Observations</p> <p>The Inspector conducted an aerial inspection of the area. No remnants were located in the area other than one aluminum boat which may or may not be associated with the project and are not of concern to the inspector.</p> <p>Notwithstanding any other administrative issue the inspector deems that no outstanding remediation concerns exist for the noted Licence and that this is the final inspection.</p>
Section 2 Non-Compliance
No instances of non-compliance
Section 3 Action Required
No actions required
Section 4 Other

Licensee or Representative	Inspector's Name
	RMO Amsel
Signature	Signature
	
Date	Date
	September 11, 2025

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---

PHOTO LOG

Date:		Authorization Number:		Camera/Model:		Inspector	
August 21, 2025		2BE-NUE1318		Nikon Coolpix		RMO AMSEL	
Photo #	1	Coordinates:	N60° 6' 41.7" W99° 59' 31.2"				



Description:

Noted items at Licence location.