

Results of Water Testing From Diamond Drilling Water Source (Before and After Drilling Completed)

Water Source For the Following Drill Hole	Source Description	Latitude			Longitude			Results Before Drilling			Results After Drilling		
		Deg	Min	Sec	Deg	Min	Sec	pH	Conductivity (uS/cm)	Temperature (°C)	pH	Conductivity (uS/cm)	Temperature (°C)
NLL-08-001	Lake	-99	59	26	60	6	38	Water Testing Equipment Not Received in Camp Until After This Point In Time			6.05	126.2	5.9
NLL-08-002	Lake	-99	59	29	60	6	49				6.56	25.9	13.7
NLL-08-003	Lake	-99	59	29	60	6	49				6.56	25.9	13.7
NLL-08-004	Lake	-99	59	29	60	6	49				6.56	25.9	13.7
NLL-08-005	Lake	-99	59	29	60	6	49				6.56	25.9	13.7
NLL-08-006	Lake	-99	59	29	60	6	49				6.56	25.9	13.7
NLL-08-007a	Lake	-99	59	29	60	6	49				6.56	25.9	13.7
NLL-08-007	Lake	-99	59	29	60	6	49				6.56	25.9	13.7
NLL-08-008	Lake	-99	59	29	60	6	49				6.56	25.9	13.7
NLL-08-009	Lake	-99	59	29	60	6	49				6.56	25.9	13.7
NLL-08-010	Swamp	-99	59	46	60	7	31	4.54	42.2	23.1	6.2	46	22.4
NLL-08-011	Swamp	-99	59	46	60	7	31	4.54	42.2	23.1	6.2	46	22.4
NLL-08-012	Lake	-100	4	38	60	5	11	6.66	73.1	13.9	6.57	75	14.3
NLL-08-013	Lake	-99	55	15	60	4	42	Erroneous Readings			5.2	53.5	18
NLL-08-014	Lake	-100	2	58	60	10	16	6.09	16.89	14.5	6.04	16.74	14.5
NLL-08-015	Lake	-100	4	38	60	5	11	6.66	73.1	13.9	6.57	75	14.3