NWB Annual	Report			Year	being report	ted:	2009	•		
License No:	2BE-NUE0810	0			ed Date: May					
				Expii	ry Date: Jun	ne 30, 2	2010			
	Project Name	e: [	Nueltin L	ake Exploration P	roject					
	Licensee:	Cameo	co Corpora	ation						$\neg$
	Mailing Addro	ess:		2121 11th Street Saskatoon, Sk S7M 1J3	West					
		-	_	nual Report (if diffees, if applicable):	erent from Name	e of Lice	nsee pleas	se clarify		]
General Back	around Infor	mation	on the P	roject (*optional):						_
	There was no	drilling	completed	d in 2009, water w Sandy Beach Lake						
Licence Requ	irements: the	e licens	see must	provide the follo	wing informa	ation ir	n accoda	nce with	1	
	Part B	▼ It	tem 2	▼						
_				disposal activiti nt; drill waste ma						
	Water Source	(s):		Water was source 99 59' 12.16"W, 5		ly Beacl	h Lake at	60 06' 3	6.67"N,	
	Water Quantity:			10/day 3/day	Quantity Allov Actual Quanti Quantity Allov Total Quantity	ity Used wable D	d Domest Drilling (cu	tic (cu.m) u.m)		
	Waste Manag ✓ Solid W ✓ Sewage ☐ Drill Wa ✓ Greywa ☐ Hazardo ☐ Other:	aste Disp e aste ter ous		sposal						
	Additional Det		wood to Ni	ualtin Laka Ladee	for diamenal !	ام ام عاد	II Carre	10 00 d s		
<b>I</b>				ueltin Lake Lodge	•		•		ey	
	water was disposed of in a pit latrine >50m from the high water mark of the lake.  Latrine was backfilled at the end of the program when the camp was removed.									

A list of	f unauthorized discharges and a summary of follow-up actions taker	n.
	Spill No.: NO REPORTS (as reported to the Spill	
	Date of Spill:	7
	Date of Notification to an Inspector:	
	Additional Details: (impacts to water, mitigation measures, short/long term mor	nitoring, etc)
Revision	ons to the Spill Contingency Plan	
IVENISIO	N/A - not applicable	▼
	The total approach	l I
	Additional Details:	
Revision	ons to the Abandonment and Restoration Plan	
	N/A - not applicable	▼
	Additional Details:	
<b>Progres</b>	ssive Reclamation Work Undertaken	
	Additional Details (i.e., work completed and future works proposed	
	All contents of the temporary camp were removed at the completic	
	program. All garbage was removed to Nueltin Lake Lodge for disp	
	Pit latrine was backfilled at the completion of the program. No evic	dence of the camp remains.
Results	s of the Monitoring Program including:	
	The CDS Co ardinates (in degrees, minutes and seconds of Is	stitude and langitude) of each
	The GPS Co-ordinates (in degrees, minutes and seconds of la location where sources of water are utilized;	initide and longitude) of each
	Details described below	_
	betails described below	•
	Additional Details:	
	60 06' 36.67"N, 99 59' 12.16"W, location of water pump was on s	shore immediately adjacent
	to the camp set up. Refer to Figure 1	, ,
	The GPS Co-ordinates (in degrees, minutes and seconds of la	titude and longitude) of each
	location where wastes associated with the licence are deposit	
	Details described below	▼
	Additional Details:	
	Pit latrine was located 50 m north-west of the camp on a sandy es	sker.
	Results of any additional sampling and/or analysis that was re	equested by an Inspector
	and the state of the stat	
	No additional sampling requested by an Inspector or the Board	▼
	I NO GOGINOTIC SCHIPLING LEGICESTER DY ALL HISDECTOL OF THE DUCK	₹

	INO additional San	ipiling requested by a	in inspector or the	board		
	Additional Det	ails: (date of reg	iest analysis d	of results, data att	ached etc)	
	/ taditional Bot	ano: (dato or roqu	doot, analysis c	7 roodito, data att	doriou, otoj	
Any other de reported.	etails on water	use or waste di	sposal reques	sted by the Boar	d by November 1	of the year being
	No additional sam	npling requested by a	n Inspector or the	Board		▼
	Additional Det	ails: (Attached or	provided belo	w)		
Any respons	ses or follow-u	p actions on ins	spection/comp	oliance reports		
		d/or compliance repo	<del>-</del>	•		▼
ı	Additional Det	ails: (Dates of Re	eport, Follow-u	p by the Licensee	e)	
Any addition	al comments	or information f	or the Roard t	o consider		
Ally addition	iai comments	or illiorillation i	or the Board t	O CONSIDER		
'						
Date Submitt		January 5th, 201			<u> </u>	_
Submitted/Pi			en, Project Lead 1-306-956-642	der, Nueltin Lake	Project	4
Contact infol	rmation:	rei: Fax:	1-306-956-639			$\dashv$
		email:		gen@cameco.con	<u> </u>	=
			ca Honoboly	30000.001	<u>··</u>	