

Cooley and Sako Drill site clean-up July 2018

Northquest Ltd



Sako -17PB070_after



Sako - 17PB070_before



Cooey - PB-11-06_PB-11-07_after



Cooey - PB-11-06_PB-11-07_before



Cooey - PB-11-08_after



Cooey - PB-11-08_before



Cooey - PB-11-09_after



Cooey - PB-11-09_before



Cooley - PB-11-10_after



Cooley - PB-11-10_before



Cooey - PB-11-11_after



Cooey - PB-11-11_before



Cooley - PB-11-12_after



Cooley - PB-11-12_before




Sako - PB-11-13_clean



Sako - PB-11-14_after




Sako - PB-11-14_PB-11-15_before



Sako - PB-11-15_after



Sako - PB-11-16_after



Sako - PB-11-16_before



Sako - PB-12-01_clean



Sako - PB-12-02_after



Sako - PB-12-03_clean



Sako - PB-14-01_after



Sako - PB-14-01_before



Sako - PB-14-02_after



Sako - PB-14-02_before



Sako - PB-14-03_after



Sako - PB-14-03_before