

## NWB Annual Report

Year being reported:

Select



2013

License No: 2BE-PEL0813

Issued Date: May 27, 2008

Expiry Date: December 31, 2013

Project Name: Amaruk

Licensee: Diamonds North Resources Ltd./ Adamera Minerals Corp.

Mailing Address: Suite 1100 - 1111 Melville Street  
Vancouver, BC  
V6E 3V6

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

same as above.

## General Background Information on the Project (\*optional):

This project was originally operated by BHP Billiton Diamonds Inc. until they decided not to continue with their option agreement. In May of 2006 a request was made that the original water license (NWB2PEL0507) be assigned to Diamonds North as we are now operator of the project. The licence was assigned to Diamonds North on June 20, 2006. In 2008 a new water licence was issued to Diamonds north to continue with their exploration efforts at Amaruk. In 2013, Diamonds North Resources amalgamated with Uranium North Resources to form Adamera Minerals Corp.

Licence Requirements: the licensee must provide the following information in accordance with

Part B



Item 2



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Cache Lake at 90° 04' 23"W, 68° 07' 35"N	
Water Quantity:	5 cu m daily	Quantity Allowable Domestic (cu.m)
	0 cu m	Actual Quantity Used Domestic (cu.m)
	90 cu m daily	Quantity Allowable Drilling (cu.m)
	0 cu m daily	Total Quantity Used Drilling (cu.m)

## Waste Management and/or Disposal

- ☐ Solid Waste Disposal  
☐ Sewage  
☐ Drill Waste  
☐ Greywater  
☐ Hazardous  
☐ Other:

Additional Details:

General: Due to the economic downturn, the remote location, and high cost of work in

the north, Diamonds North decided after the 2011 field season to cease work on the Amaruk Project. In 2012, no exploration work was conducted and abandonment and restoration of the area commenced.

All drill sites from previous years were inspected upon completion of the hole, all drill sumps were backfilled and leveled, drill collars were cut off to ground level, and drill pads returned as near as possible to their original state. All garbage and fuel drums were collected and flown to camp for incineration or removal to an approved disposal location.

All buildings, contents, and equipment including generators, pumps, hoses, incinerator, drill and ancillary equipment were dismantled and removed from the property. No fuel remains at the camp or at fuel cache locations on the property. Empty drums were backhauled to Kugaaruk/Yellowknife/Churchill during the course of the program and the remaining drums have been removed from Apron B at the Kugaaruk Airport. The grey water sump was in-filled and the latrine sump was buried at the time of the last demobilization of the camp. Abandonment and restoration of the camp, drill sites and fuel caches has been completed.

#### A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No unauthorized discharges or spills

#### Revisions to the Spill Contingency Plan

N/A - not applicable



Additional Details:

#### Revisions to the Abandonment and Restoration Plan

N/A - not applicable



Additional Details:

#### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

See above.

### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Not Applicable (N/A)

Additional Details:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Not Applicable (N/A)

Additional Details:

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

No inspection and/or compliance report issued by INAC

Additional Details: (Dates of Report, Follow-up by the Licensee)

--

Any additional comments or information for the Board to consider

--

**Date Submitted:**

May 28, 2015

**Submitted/Prepared by:**

Zoe Pratt

**Contact Information:**

**Tel:** 604-689-2010

**Fax:** 604-484-7143

**email:** [z.pratt@adamera.com](mailto:z.pratt@adamera.com)