

NWB Annual Report

Year being reported: 2008



License No: NWB2PIX0510

Issued Date: September 9, 2005

Expiry Date: August 1, 2010

Project Name: Pix Project

Licensee: Ashton Mining (Northwest Territories) Ltd.

Mailing Address: Unit 116-980 West 1st Street
North Vancouver, BC
V7P 3N4

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Ashton Mining (Northwest Territories) Ltd. is a wholly owned subsidiary of Stornoway Diamond Corporation.

General Background Information on the Project (*optional):

No water use or waste disposal was conducted under the authority of this license during the period being reported.

Licence Requirements: the licensee must provide the following information in accordance with

Select



Select



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

N/A

Water Quantity:

5 cu.m/day

Quantity Allowable Domestic (cu.m)

0 cu.m/day

Actual Quantity Used Domestic (cu.m)

N/A

Quantity Allowable Drilling (cu.m)

N/A

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☐ Solid Waste Disposal☐ Sewage☐ Drill Waste☐ Greywater☐ Hazardous☐ Other:

□ Spill:

Additional Details:

No waste was produced during the reporting period.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A)



Additional Details:

N/A

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A) ▼

Additional Details:

N/A

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

N/A

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

N/A

Any additional comments or information for the Board to consider

N/A

Date Submitted:

March 31, 2009

Submitted/Prepared by:

Nicole Westcott, Land Administrator

Contact Information:**Tel:** 604-983-7750**Fax:** 604-987-7107**email:** nwestcott@stornowaydiamonds.com