

NWB Annual Report

Year being reported:

2010

License No: NWB2PIX0510

Issued Date:

September 9, 2005

Expiry Date:

August 1, 2010

Project Name:

Pix Project

Licensee:

Ashton Mining (Northwest Territories) Ltd.

Mailing Address:

Unit 116-980 West 1st Street
 North Vancouver, BC
 V7P 3N4

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Ashton Mining (Northwest Territories) Ltd. is a wholly owned subsidiary of Stornoway Diamond Corporation.

General Background Information on the Project (*optional):

No water use or waste disposal was conducted under the authority of this license during the period being reported.

Licence Requirements: the licensee must provide the following information in accordance with

Select

Select

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

N/A

Water Quantity:

5 cu.m/day

Quantity Allowable Domestic (cu.m)

0 cu.m/day

Actual Quantity Used Domestic (cu.m)

N/A

Quantity Allowable Drilling (cu.m)

N/A

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☐ Solid Waste Disposal

☐ Sewage

☐ Drill Waste

☐ Greywater

☐ Hazardous

☐ Other:

Additional Details:

No waste was produced during the reporting period.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

N/A

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

N/A

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed

Additional Details:

N/A

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

N/A

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A)

Additional Details:

N/A

N/A

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A)

Additional Details:

N/A

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

N/A

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC

Additional Details: (Dates of Report, Follow-up by the Licensee)

N/A

Any additional comments or information for the Board to consider

This license expired on August 1, 2010. No water was ever used or waste disposed of under the authority of this license. An official request to close/cancel this license has been submitted to the Nunavut Water Board.

Date Submitted:

October 19, 2012

Submitted/Prepared by:	Nicole Westcott, Manager of Regulatory and Community Affairs - Exploration
Contact Information:	Tel: 604-983-7750
	Fax: 604-987-7107
	email: nwestcott@stornowaydiamonds.com

