

NWB Annual Report

Year being reported:

2018

License No: 2BE-PKR1621

Issued Date: March 7, 2016

Issued Date:	March 7, 2019
Expiry Date:	October 30, 2021

Project Name: Parker Lake Exploration Project

Licensee: Agnico Eagle Mines Ltd.

Mailing Address: C.P. 87, 765 chemin de la mine Goldex
Val-d'Or, Qc
J9P 4N9

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B

Item 2

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Proximal lakes and ponds

Water Quantity:

5m³/day

Quantity Allowable Domestic (cu.m)

0

Actual Quantity Used Domestic (cu.m)

294m³/day

Quantity Allowable Drilling (cu.m)

0

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

No exploration activities were conducted in 2018 under this water licence. 2 seacans containing contaminated soil were transported during the winter from the camp site to be disposed of.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:

(as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector: _____

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Spill No.:

](as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector: _____

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Decontamination activities were conducted as detailed in the attached spill situation reports.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A)

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A)

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:	December 6, 2018
Submitted/Prepared by:	David Frenette, Environmental Coordinator
Contact Information:	Tel: 819.874.5980 ext. 3622
	Fax:
	email: david.frenette@agnicoeagle.com